

NWB Annual Report Year being reported: 2020

License No: 2BE-PKR1621

Issued Date: March 7, 2016

Expiry Date: October 30, 2021

Project Name: Parker Lake Exploration Project

Licensee: Agnico Eagle Mines Ltd.

Mailing Address: 765 chemin de la mine Goldex
Val-d'Or, Qc
J9P 7G4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B

Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Proximal lakes and ponds	
Water Quantity:	5m³/day	Quantity Allowable Domestic (cu.m)
	0 m³/day	Actual Quantity Used Domestic (cu.m)
	294m³/day	Quantity Allowable Drilling (cu.m)
	0 m³/day	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal

☐ Sewage

☐ Drill Waste

☐ Greywater

☐ Hazardous

☐ Other:

Additional Details:

No activities conducted under this licence in 2020.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No unauthorized discharge in 2020.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No reclamation work undertaken in 2020. Material and equipment backhaul is planned to be conducted during the winter 2021.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)



Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)



Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC



Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:	March 22, 2021
Submitted/Prepared by:	David Frenette, Environmental Coordinator
Contact Information:	Tel: 819.874.5980 ext. 4103622
	Fax:
	email: david.frenette@agnicoeagle.com

