



AGNICO EAGLE

ANNUAL REPORT 2024: WATER LICENCE 2BE-PKR2126

**PRESENTED TO
NUNAVUT WATER BOARD**

FEBRUARY 2025

Contact:

Agnico Eagle Mines Ltd.

David Frenette

Environmental Coordinator

765 Chemin de la mine Goldex

Val-d'Or, Québec, J9P 7G4

david.frenette@agnicoeagle.com

Water license 2BE-PKR2126, Part B item 2:

2. The Licensee shall file an Annual Report on the Appurtenant Undertaking with the Board no later than March 31st of the year following the calendar year being reported, containing the following information:

- a. Summary report of Water use and Waste disposal activities for the reporting period including the following;
 - *No exploration activities were conducted in 2024 under this water licence and no water was used and no waste was generated.*
 - i) Quantity of Water (in cubic metres/year) obtained for domestic and other purposes from sources on, in or flowing through Inuit-Owned Lands;
 - *No water used in 2024.*
 - ii) Quantity of Water (in cubic metres/year) obtained for domestic and other purposes from sources on, in or flowing through Crown Lands;
 - *No water used in 2024.*
 - iii) Quantity of Waste disposed of at on-site Waste disposal facility;
 - *No waste disposed of in 2024.*
 - iv) Quantity of Waste backhauled to approved facility for disposal;
 - *No waste backhauled in 2024.*
- b. List of unauthorised discharges and as summary of follow-up action taken;
 - *No unauthorized discharge occurred in 2024.*
- c. Any revisions to the Spill Contingency Plan and Abandonment and Restoration Plan, as required by Part B, Item 7, submitted in the form of and Addendum;
 - *No revision proposed.*
- d. Description of all progressive and or final reclamation work undertaken, including photographic records of site conditions before, during and after completion of operations;
 - *Details are provided in section (i) below.*

- e. Report all artesian flow occurrences as required under Part F, Item 3;
- *No artesian flow occurrences in 2024.*
- f. Details pertaining to location of sump (s) and drill holes;
- *No sump or drill hole done in 2024 under this water licence.*
- g. Summary of all information requested and results of the Monitoring Program;
- *No monitoring program was applicable in 2024 as no exploration activities were conducted.*
- h. Summary of public consultation/participation, describing consultation with local organizations and residents of the nearby communities, if any were conducted;
- *No summary to present as exploration activities in 2024 did not include works in the area covered by this licence.*
- i. Any other details on Water use and Waste disposal requested by the Board by the 1st of November of the year being reported.
- *The Board requested that Agnico Eagle provide a brief summary of the work done to address the non-compliance issue identified by the Inspector in 2022 for water licence 2BE-PKR2126. This issue was related to nails and wood left on the former campsite.*
- The CIRNAC inspector conducted a new site inspection on July 12th, 2024, for water licence 2BE-PKL2126 and concluded that:*
- *No items of non-compliance were found.*
 - *No actions were required.*

In August 2024, Agnico Eagle visited the site to remove wooden blocks and divert metal. These materials were transported by helicopter to the Meliadine mine site for proper disposal. The site is now considered closed.