

**WATER LICENCE INSPECTION FORM**☒ Original  
☐ Follow-Up Report

<b>Licensee</b>	<b>Licensee Representative</b>
Agnico Eagle Mines Limited	David Frenette
<b>Licence No. / Expiry</b>	<b>Representative's Title</b>
2BE-PTR1621/ October 30 <sup>th</sup> , 2021	Environmental Coordinator
<b>Land Authorization No. / Purpose</b>	<b>Other Authorization</b>
N2016C0002 (Peter/Parker Exploration Drilling)	2BE-PRK1621(Parker Exploration Camp)
<b>Date of Inspection</b>	<b>Inspector</b>
July 26 <sup>th</sup> , 2017	WRO Wilson
<b>Activities Inspected</b>	
<input checked="" type="checkbox"/> Camp <input checked="" type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input checked="" type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage	
<input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: Water Discharge <input type="checkbox"/> Other:	

<b>SECTION 1</b>	<input checked="" type="checkbox"/> <b>Comments (s. __)</b>	<input type="checkbox"/> <b>Non-Compliance with Act or Licence (s. __)</b>	<input type="checkbox"/> <b>Action Required (s. __)</b>
On July 26 <sup>th</sup> , 2017 a regularly scheduled compliance inspection was conducted of Agnico Eagle Mines Ltd.'s ('AEM') Fox/Peter Lake Project.			
<i>Observations</i>			
1. A total of four holes -FOX16-002, FOX16-007A, FOX16-005, FOX16-008 and FOX16-011- were inspected.			
2. All of the drill holes were located on crown land.			
3. The drill sites have been reclaimed to the satisfaction of the inspector with the casings removed and the cuttings placed in a natural depression proximal to the hole.			
4. No camp is constructed under the water licence; AEM utilizes accommodation at Parker Lake or Meliadine Camp.			
<b>SECTION 2</b>	<input type="checkbox"/> <b>Comments (s. __)</b>	<input checked="" type="checkbox"/> <b>Non-Compliance with Act or Licence (s.2)</b>	<input type="checkbox"/> <b>Action Required (s. __)</b>
No concerns at this time.			
<b>SECTION 3</b>	<input type="checkbox"/> <b>Comments (s. __)</b>	<input type="checkbox"/> <b>Non-Compliance with Act or Licence, (s. __)</b>	<input checked="" type="checkbox"/> <b>Action Required (s.3)</b>
The inspector was satisfied with the overall operation of the Fox/Peter projects, noting no outstanding concerns related to the licence.			

<b>Licensee or Representative</b>	<b>Inspector's Name</b>
	C. Wilson
<b>Signature</b>	<b>Signature</b>
	<i>Christie Wilson</i>
<b>Date</b>	<b>Date</b>
	October 16th, 2017

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

**Attached:** Photo Log 2BE-PTR1621, - July 26th, 2017

cc. Erik Allain, Manager Field Operations, INAC  
David Frenette, Environmental Coordinator, AEM  
Mario Bolduc, P.geo, AEM  
Manager, Licensing, Nunavut Water Board