

NWB Annual Report

Year being reported:

2016

License No: Issued Date:
Expiry Date:

Project Name:

Licensee:

Mailing Address:

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	<input type="text" value="Proximal lakes and ponds"/>	
Water Quantity:	<input type="text" value="0"/>	Quantity Allowable Domestic (cu.m)
	<input type="text" value="0"/>	Actual Quantity Used Domestic (cu.m)
	<input type="text" value="299m³/day"/>	Quantity Allowable Drilling (cu.m)
	<input type="text" value="35m³/day (total 425m³)"/>	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
- ☐ Sewage
- ☒ Drill Waste
- ☐ Greywater
- ☒ Hazardous
- ☐ Other:

Additional Details:

The solid and hazardous wastes generated during the drilling were transported to the Meliadine camp site and disposed of according the Meliadine procedures.
The drill cuttings were disposed of near of the drill sites.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No unauthorized discharge in 2016.

Revisions to the Spill Contingency Plan

SCP addendum attached for Board consideration



Additional Details:

Revisions to the Abandonment and Restoration Plan

No Abandonment and Restoration (AR) Plan submitted or approved



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Drill casings, material and equipment were removed of the drilling sites.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached



Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached



Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

In attachment, a photographic record.

Date Submitted:

December 9, 2016

Submitted/Prepared by:

David Frenette, Environmental Coordinator

Contact Information:

Tel: (819) 874-5980 ext.3622

Fax:

email: david.frenette@agnicoeagle.com