

September 16, 2010

**CAMECO CORPORATION** 

Corporate Office 2121 – 11th Street West Saskatoon, Saskatchewan Canada S7M 1J3

Tel 306.956.6200 Fax 306.956.6201 www.cameco.com

Karén Kharatyan Technical Advisor Nunavut Water Board Box 119 Gjoa Haven, NU X0B 1J0

Dear Ms Kharatyan:

## Licence 2BE-QAM0813, Cameco Corporation 2009 Annual Report, submitted under Part B, Item 2

Please find enclosed a copy of the complete annual report with an additional page that lists GPS co-ordinates of all locations where wastes associated with licence are deposited. The page was mistakenly not included with the original e-mail.

Yours truly, CAMECO CORPORATION

Rebecca Hunter

Project Geologist, Nunavut & N.W.T. e-mail: rebecca hunter@cameco.com

Attachments

RH:ml

NWB Annua	l Report	Year being reported: 2009 ▼	
License No:	2BE-QAM0813	Issued Date: June 2, 2008	
		Expiry Date: September 31, 2013	
	Project Name	Turqavik - Aberdeen Project or (Qamanaarjuk Lake Project)	
	_		
	Licensee:	Rebecca Hunter	
	Mailing Addre	Sas:  Cameco Corporation 2121-11th St W Saskatoon, Saskatchewan S7M 1J3	
		pany filing Annual Report (if different from Name of Licensee please clarify	
		een the two entities, if applicable):	
	Same as abov	). 	
General Bac	kground Inforn	nation on the Project (*optional):	
with	initiated in 200 program consi- as ground grav uirements: the	season included further construction of the exploration camp that was and continued throughout 2007 and 2008. The 2009 exploration sted of diamond drilling, prospecting, mapping and sampling, as well ity geophysical survey.  Ilicensee must provide the following information in accodance	
_		use and waste disposal activities, including, but not limited to: method	
_		d greywater management; drill waste management; solid and hazardou	S
waste manaç	Water Source( Water Quantity		
		er IS	
	Summary Reg	ort:	

A summary report of water use and waste disposal activities includes a detailed description of methods of obtaining water and its treatment for domestic use, and description of procedures for greywater and sewage management. The following report outlines the water use and waste disposal practices during the Turqavik – Aberdeen Projects 2009 field season.

Potable water for use at the exploration camp is taken from Qamanaarjuk Lake, located down the hill from the camp. From the lake, water is pumped with a gasolinedriven high-pressure pump. The intake location is approximately 7 m away from the shore. There, the suction hose is equipped with a standard 2" (3.22 cm) pond strainer, ensuring no organisms get accidentally sucked in. Through the 1" (2.54 cm) supply hose, water is pumped up the hill into a sheltered 1000 gallon (3.8 m3) tank. During the transfer to a smaller tank (capacity of approximately 300 gallons or 1.1 m3), located inside the main building, water is filtered and treated by UV radiation. This filter is a UV20 Series PURA set-up for small commercial application. During the filtering process, water is passed through a series of polyester filters that first remove sediments 10 μ and larger, and then remove any particles as small as 5 μ. In addition, the system includes a charcoal filter and, as a final treatment step, a large UV filter. This filtered and treated water is only used for consumption, preparation of foods, showering, washing of kitchen supplies and laundry. On average, approximately 1 m3 of water is used daily. Water intake was monitored by a mounted standard meter that is used in municipal supply distribution systems (nutating disc displacement flow meter). Logs of pumped water are kept and are included with this report.

At the camp there are four 200 L capacity sumps. All greywater from domestic use (from cooking, dish washing, showering, and washing machine) is disposed into either one of the sumps. These sumps are located at a distance of well above the minimum 30 metres from the high water mark of the lake, near the main two buildings (used for kitchen, dry and office). The sumps are cribbed with perforated steel drums. The kitchen sump is also equipped with a commercial baffled grease trap for a more efficient waste separation. The locations of the three sumps used for showering, laundry and washing of kitchen supplies have been moved 1 m down slope from their original spot described in the 2008 water report. The kitchen sump was moved to a more adequate gravel-rich spot. The move was necessary to accommodate for the rehabilitation of the old sumps that are not draining water properly. In order to fix the old sumps, burning of the residual waste with propane and breaking down of the soap-rich residue, if applicable, are required.

All sewage and domestic waste are incinerated. On premises, there are two incinerators. One incinerator is The Original Burnadette supplied by Nugget Expediting Ltd. It has floor dimensions of 25" x 25" (63.5 x 63.5 cm) and contains a Beckett Industrial Burner with own diesel fuel supply. This incinerator is used for a fast evaporation of liquids before all waste is transferred to the second incinerator. The second incinerator is a SmartAsh cyclonic barrel burner manufactured by Elastec Inc. It consists of a 208 L capacity drum with manual fuel supply. During incineration, waste is reduced to approximately 3% ashes by volume. The incinerator is designed to use liquid fuel such as diesel or Jet A. All sewage, kitchen food waste, and solid waste (such as glass and plastic jars, paper, wood shavings, used oil, etc.) are incinerated and turned into ash.

Incinerated ash is removed by hand, packed into cardboard boxes and wrapped in

Incinerated ash is removed by hand, packed into cardboard boxes and wrapped in two plastic bags for additional security. These packages are then transported to municipal disposal grounds in Baker Lake.

At the drill site, water is used for circulation down the drill hole to cut through the rock and to wash out the hole. The length of the water line for the drill ranged from 50 to 1,500 m. Water was pumped from the closest lake that was also large enough to supply approximately 35 m3 of water per day. Water intake was monitored by the pump set-up itself with a moving rate of 10 gallons/minute (approximately 38 litres/minute or 0.038 m3/min). Circulated water ran off from the drill site and percolated into the ground. The cuttings were directed into natural depressions of the terrain. One drill hole intersected weak uranium mineralization. The cuttings were separated using a centrifuge of the drill's water recycling system, gathered into a chemically resistant industrial-size vinyl bag, and levels of uranium concentration were monitored daily. The radiation level of the cuttings fell below the 0.005 mSv/hr, which is equivalent to 0.05% uranium concentration. As indicated by the INAC Land Use Permit N2008C0007 only cuttings that exceed 0.05% uranium concentration are to be collected and disposed either down the drill hole or by other acceptable means. After the drill hole was completed the cuttings were removed from the vinyl bags and distributed in natural depressions directly around the drill site.

All fuel drums at the camp and at the airstrip were stored in berms. At the camp, the generator is connected to a double-walled 250 gallon (0.95 m3) metal fuel tank by copper fuel lines. For use at the camp 9 berms were purchased, 8 of which have dimensions of 10' x 10' x 1' (3 x 3 x 0.3 m) and can hold 15 drums. And one berm has dimensions of 10' x 15'x 1' (3 x 4.6 x 0.3 m) to hold approximately 25 drums. The berms are made of XR-5 high grade chemically resistant vinyl fabric. Rain water that collects in the berms is absorbed, filtered and returned as greywater. All used absorbents are incinerated. There are two extra large berms at the main airstrip. One berm has the dimensions of 30' x 60' (9 x 18 m) to hold up to 300 drums of fuel, and the second berm has the dimensions of 50' x 50' (15 x 15 m) to hold a maximum of 416 drums of fuel. At the drill sites fuel is stored in double-walled metal containers.

A list of unau	uthorized disc	harges and a sumi	mary of follow-up actions	taken.	
	Spill No.:	n/a	(as reported to the Spill Ho	ot-line)	
	Date of Spill:				
	Date of Notific	ation to an Inspecto	r:		
	Additional Det	ails: (impacts to water, i	mitigation measures, short/long te	rm monitoring, etc)	
Revisions to	the Spill Con	tingency Plan			
	SCP submitted ar	nd approved - no revisior	required or proposed		_
	Additional Det	ails:			

Revisions to	the Abandonment and Restoration Plan
	AR plan submitted and approved - no revision required or proposed
	Additional Details:
	Additional Botano.
Progressive	Reclamation Work Undertaken
riogiessive	Additional Details (i.e., work completed and future works proposed)
	Exploration program is ongoing with a similar objective for 2010 field season.
Results of th	e Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
	each location where sources of water are utilized;
	Details attached
	- Johans anderiod
	Additional Details:
	Report on locations where sources of water are utilized with corresponding photos is
	attached.
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;  Details described below
	Additional Details:
	See attached Excel sheet for GPS coordinates. At the camp, four sumps are used for disposal of greywater, as well as sewage and other waste are incinerated. Circulated water at the drill sites is allowed to percolate back into the ground on location.
	Results of any additional sampling and/or analysis that was requested by an Inspector
	No additional sampling requested by an Inspector or the Board
	Additional Details: (date of request, analysis of results, data attached, etc)
_	etails on water use or waste disposal requested by the Board by November 1 of the year
being report	ed.
	No additional sampling requested by an Inspector or the Board   ▼
	Additional Details: (Attached or provided below)
	Table 1 and

p actions on inspection/compliance reports
received by the Licensee (Date):
ails: (Dates of Report, Follow-up by the Licensee) v inspections in 2007 and 2008:
or secondary containment of fuel drums at the camp, and at the drill ed in double-walled metal containers. erators are used for waste management.
or information for the Board to consider
March 30, 2010  Rebecca Hunter  Tel: (306) 956-6279  Fax: (306) 956-6390  email: rebecca_hunter@cameco.com

## Coordinates for locations where water is pumped

	La	titude		Lo	ngitud	е
Source Description	o Deg	, Min	, Sec	o Deg	Min	, Sec
Water pump for the camp/suction hose	64	37	43.1	97	59	27.9
General camp location	64	37	43.0	97	59	40.1
ABR-003	64	9	55.1	98	30	15.6
ABR-004	64	18	48.3	98	25	26.1
ABR-005	64	18	35.0	98	25	17.8
ABR-006	64	18	34.8	98	21	39.2
ABR-007	64	19	45.9	98	19	39.7
ABR-008	64	20	51.5	98	17	49.6
TUR-006	64	20	31.4	97	59	32.6
TUR-007	64	23	21.4	98	7	3.6
TUR-008	64	23	28.0	98	6	54.4
TUR-009	64	24	18.9	98	9	1.1
TUR-010	64	24	13.3	98	5	34.2
TUR-011	64	22	58.1	98	7	0.9
TUR-012	64	27	41.8	97	40	5.6
TUR-013	64	28	59.3	97	31	43.5

## Coordinates for locations of areas of waste disposal

Location Description (type)	La	Latitude			Longitude		
	o Deg	Min	, Sec	o Deg	Min	, Sec	
Kitchen Sump	64	37	43.3	97	59	39.6	
Kitchen Sump #2	64	37	43.4	97	59	40.4	
Sump by the Office Building	64	37	43.9	97	59	39.5	
Shower/Dry Sump	64	37	43.7	97	59	39.0	
Incinerator	64	37	38.6	97	59	35.2	
ABR-003	64	9	55.9	98	30	22.3	
ABR-004	64	18	41.9	98	25	13.2	
ABR-005	64	18	34.7	98	25	36.0	
ABR-006	64	19	8.6	98	20	41.6	
ABR-007	64	19	19.6	98	21	8.9	
ABR-008	64	20	46.4	98	18	17.0	
TUR-006	64	20	39.7	97	58	58.0	
TUR-007	64	23	33.3	97	8	34.5	
TUR-008	64	23	33.5	98	7	36.6	
TUR-009	64	24	17.4	98	8	42.5	
TUR-010	64	24	6.8	98	4	60.0	
TUR-011	64	22	59.8	98	7	54.1	
TUR-012	64	27	42.3	98	40	1.8	
TUR-013	64	29	4.7	97	31	23.7	

Date	Meter	Total Water	Comments
	Reading	Pumped (m <sup>3</sup> )	
25-Apr-09			
26-Apr-09			
27-Apr-09			
28-Apr-09			
29-Apr-09			
30-Apr-09			
01-May-09			
02-May-09			
03-May-09		1.10	Camp is open for construction and geophysics crew
04-May-09			
05-May-09			
06-May-09			
07-May-09			
08-May-09			
09-May-09			
10-May-09			
11-May-09			
12-May-09			
13-May-09		1.10	
14-May-09			
15-May-09			
16-May-09			
17-May-09			
18-May-09			
19-May-09		4.50	
20-May-09			
21-May-09			
22-May-09			
23-May-09			
24-May-09		4.50	
25-May-09			
26-May-09			
27-May-09			
28-May-09			
29-May-09			Turqavik-Aberdeen 2009 Field Season officially begins
30-May-09			
31-May-09			
	May Total:	11.20	
01-Jun-09		4.50	
02-Jun-09			
03-Jun-09			
04-Jun-09			
05-Jun-09			
06-Jun-09		4.50	
07-Jun-09			
08-Jun-09			
09-Jun-09			
10-Jun-09		4.50	
11-Jun-09			
12-Jun-09			

Date	Meter	Total Water	Comments
_ 4.0	Reading	Pumped (m <sup>3</sup> )	
13-Jun-09		4.10	
14-Jun-09			
15-Jun-09			
16-Jun-09		4.30	
17-Jun-09			
18-Jun-09			
19-Jun-09		4.50	
20-Jun-09			
21-Jun-09			
22-Jun-09	83.31		Started using a meter
23-Jun-09	87.31	4.00	
24-Jun-09			
25-Jun-09			
26-Jun-09	91.06	3.75	
27-Jun-09			
28-Jun-09			
29-Jun-09	95.08	4.02	
30-Jun-09			
	une Total:	38.17	
	tive Total:	49.37	
01-Jul-09			
02-Jul-09		3.45	
03-Jul-09			
04-Jul-09			
05-Jul-09	102.41	3.88	
06-Jul-09			
07-Jul-09			
08-Jul-09		4.70	
09-Jul-09		4.72	
10-Jul-09			
11-Jul-09		2.22	
12-Jul-09 13-Jul-09		3.33	
13-Jul-09 14-Jul-09			
15-Jul-09		3.37	
16-Jul-09		5.51	
17-Jul-09		4.72	
18-Jul-09		7.72	
19-Jul-09			
20-Jul-09		4.47	
21-Jul-09		1. 77	
22-Jul-09			
23-Jul-09			
24-Jul-09		4.82	
25-Jul-09			
26-Jul-09			
27-Jul-09		5.68	
28-Jul-09			
29-Jul-09			

Dete	Motor	Total Motor	Comments
Date	Meter Reading	Total Water	Comments
20 1.1 00		Pumped (m <sup>3</sup> )	
30-Jul-09 31-Jul-09	136.61	3.53	
	otal Total:	44.07	
	tive Total:	41.97 91.34	
01-Aug-09		91.34	
02-Aug-09		4.21	
03-Aug-09	140.02	7.21	
04-Aug-09			
05-Aug-09	145	4.18	
06-Aug-09			
07-Aug-09	148.5	3.50	
08-Aug-09			
09-Aug-09	151.06	2.56	
10-Aug-09			
11-Aug-09			
12-Aug-09	155.5	4.44	
13-Aug-09			
14-Aug-09			
15-Aug-09	159.74	4.24	
16-Aug-09			
17-Aug-09			
18-Aug-09	163.6	3.86	
19-Aug-09			
20-Aug-09			
21-Aug-09			
22-Aug-09 23-Aug-09	167.66	4.06	
23-Aug-09 24-Aug-09	107.00	4.00	
25-Aug-09			
26-Aug-09			
27-Aug-09			
28-Aug-09			
29-Aug-09			
30-Aug-09	172.44	4.78	
31-Aug-09			
Mon	thly Total:	35.83	
Cummula	tive Total:	127.17	
01-Sep-09			
02-Sep-09			
03-Sep-09			
04-Sep-09			
05-Sep-09			
06-Sep-09			
	thly Total:	0.00	
Cummula	tive Total:	127.17	

Camp shut down for the season on September 6<sup>th</sup>. The meter was taken down.

Date	Amount of Hours the Drill Operated	Gallons of Water Used	Litres of Water Used	Amount of water used in m <sup>3</sup>	Comments
08-Jun-09	9.5	5,700	21,546	21.55	Drilling started on TUR-006
09-Jun-09	21.5	12,900	48,762	48.76	Drilling TUR-006
10-Jun-09	21.5	12,900	48,762	48.76	Drilling TUR-006
11-Jun-09	19.5	11,700	44,226	44.23	Drilling TUR-006
12-Jun-09	11.5	6,900	26,082	26.08	Finished TUR-006, cement and tear down
13-Jun-09		0	0	0.00	Tear down of TUR-006 and drill move
14-Jun-09	11.0	6,600	24,948	24.95	Move to ABR-003, cased and start drilling
15-Jun-09	21.0	12,600	47,628	47.63	Drilling ABR-003
16-Jun-09	12.5	7,500	28,350	28.35	Finished ABR-003, cement and start tear down
17-Jun-09	9.0	5,400	20,412	20.41	Move to ABR-004, cased and started drilling
18-Jun-09	22.0	13,200	49,896	49.90	Drilling ABR-004
19-Jun-09	7.5	4,500	17,010	17.01	Finished ABR-004, cement and tear down
20-Jun-09	7.5	4,500	17,010	17.01	Move and started casing TUR-007
21-Jun-09	23.5	14,100	53,298	53.30	Casing TUR-007 and then drilling
22-Jun-09	21.5	12,900	48,762	48.76	Drilling TUR-007
23-Jun-09	21.0	12,600	47,628	47.63	Drilling TUR-007
24-Jun-09	12.0	7,200	27,216	27.22	Finished TUR-007, cement, tear down; move to TUR-008, cased, drill
25-Jun-09	23.0	13,800	52,164	52.16	Drilling TUR-008
26-Jun-09	23.0	13,800	52,164	52.16	Drilling TUR-008
27-Jun-09	11.5	6,900	26,082	26.08	Finished TUR-008, cement and tear down
28-Jun-09	13.0	7,800	29,484	29.48	Move to TUR-009, casing and drilling
29-Jun-09	22.5	13,500	51,030	51.03	Drilling TUR-009
30-Jun-09	6.0	3,600	13,608	13.61	Finished TUR-009, cement, tear down and move to TUR-010
	Monthly Total:	210,600	796,068	796.07	

Total number of days the drill operated:

22

Average of water use per day for June:

36.18

Date	Amount of Hours the Drill Operated	Gallons of Water Used	Litres of Water Used	Amount of water used in m <sup>3</sup>	Comments
01-Jul-09	15.0	9,000	34,020	34.02	Drilling TUR-010
02-Jul-09	22.0	13,200	49,896	49.90	Drilling TUR-010
03-Jul-09	22.0	13,200	49,896	49.90	Drilling TUR-010

Date	Amount of Hours the Drill Operated	Gallons of Water Used	Litres of Water Used	Amount of water used in m <sup>3</sup>	Comments
04-Jul-09	6.0	3,600	13,608	13.61	Finished TUR-010, cement and start move
05-Jul-09	15.0	9,000	34,020	34.02	Move, case and drill ABR-005
06-Jul-09	20.0	12,000	45,360		Drilling ABR-005, lost hole at night shift
07-Jul-09	17.0	10,200	38,556		Started casing ABR-005b
08-Jul-09	23.0	13,800	52,164		Casing and drilling ABR-005b
09-Jul-09	12.0	7,200	27,216		Ream ice back to end of hole
10-Jul-09	23.0	13,800	52,164		Drilling ABR-005b
11-Jul-09	5.0	3,000	11,340		Finished ABR-005b, tear down and move to ABR-006
12-Jul-09	14.5	8,700	32,886		Move, casing and drilling ABR-006
13-Jul-09	17.5	10,500	39,690		Drilling ABR-006
14-Jul-09	15.0	9,000	34,020		Finished ABR-006, move, case and drill ABR-007
15-Jul-09	14.5	8,700	32,886		Drilling ABR-007
16-Jul-09	18.0	10,800	40,824		Drilling ABR-007
17-Jul-09	13.0	7,800	29,484		Finished ABR-007, cement, move to ABR-008
18-Jul-09	12.5	7,500	28,350		Casing and drilling ABR-008
19-Jul-09	21.5	12,900	48,762		Drilling ABR-008
20-Jul-09	23.0	13,800	52,164		Drilling ABR-008
21-Jul-09	17.0	10,200	38,556		Drilling ABR-008; set up a recycle system
22-Jul-09	21.5	12,900	48,762		Drilling ABR-008
23-Jul-09	10.0	6,000	22,680	22.68	Finished ABR-008, cement and tear down
24-Jul-09	4.0	2,400	9,072	9.07	Move to TUR-011 and start casing
25-Jul-09	18.5	11,100	41,958	41.96	Casing and drilling TUR-011
26-Jul-09	20.5	12,300	46,494		Drilling TUR-011
27-Jul-09	16.5	9,900	37,422		Finished TUR-011, cement and tear down
28-Jul-09	11.5	6,900	26,082		Move to TUR-012 and start casing
29-Jul-09	23.5	14,100	53,298	53.30	Casing and drilling TUR-012
30-Jul-09	23.5	14,100	53,298		Drilling TUR-012
31-Jul-09	23.5	14,100	53,298	53.30	Drilling TUR-012
	Monthly Total:	297,600	1,124,928	1124.93	
Cum	mulative Total:	508,200	1,920,996	1921.00	

Total number of days the drill operated:

31

Average of water use per day for July:

36.29

Date	Amount of Hours the Drill Operated	Gallons of Water Used	Litres of Water Used	Amount of water used in m <sup>3</sup>	Comments
01-Aug-09	19.5	11,700	44,226	44.23	Drilling TUR-012
02-Aug-09	13.0	7,800	29,484	29.48	Finished TUR-012, cement and tear down
03-Aug-09	10.5	6,300	23,814	23.81	Moving to TUR-013, casing and drilling
04-Aug-09	18.0	10,800	40,824	40.82	Drilling TUR-013
05-Aug-09	4.0	2,400	9,072	9.07	TUR-013A lost, cement; drill move to the side, casing, drill TUR-013B
06-Aug-09	19.5	11,700	44,226	44.23	Drilling TUR-013B
07-Aug-09	21.0	12,600	47,628	47.63	Drilling TUR-013B
08-Aug-09	23.0	13,800	52,164	52.16	Drilling TUR-013B
09-Aug-09	20.5	12,300	46,494	46.49	Drilling TUR-013B
10-Aug-09	7.5	4,500	17,010	17.01	Finished TUR-013B and cemented; tear down
11-Aug-09	0	0	0	0.00	Tearing down the drill for the winter
12-Aug-09	0	0	0	0.00	Tearing down the drill for the winter
Monthly Total: 93,9		93,900	354,942	354.94	
Cummulative Total:		602,100	2,275,938	2,275.94	

Total number of days the drill operated: 10

Average of water use per day for August: 35.49