NWB Annual	Report	Year being reported: 2006 ▼
License No:	2BE-RB0608	Issued Date: May 23, 2006 Expiry Date: August 31, 2008
	r	
	Project Name:	Roche Bay
	Licensee: Roche	Bay plc
	Mailing Address:	Suite 202, Parnaivik Building PO Box 2021 Iqaluit, NU X0A 0H0
		filing Annual Report (if different from Name of Licensee please clarify e two entities, if applicable):
General Bacl	kground Information	on the Project (*optional):
Licence Req with	1 1	see must provide the following information in accodance
	iter; sewage and gre	and waste disposal activities, including, but not limited to: methods of eywater management; drill waste management; solid and hazardous
	Water Source(s): Water Quantity:	Camp domestic, Drilling source 1, Drilling source 2, Drilling 100
ı	Waste Management Solid Waste Disp Sewage Drill Waste Greywater Hazardous Other: Additional Details:	posal
		en off site to the Hall Beach dump. in a sump as per regulations. ed in a sump.

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.: Date of Spill:	N/A	(as repo	rted to the S _I	oill Hot-lin	ne)		
	Additional Det	ails: (impacts to water,	mitigation r	neasures, short/	long term n	nonitoring, et	tc)	-
Revisions to	the Spill Con	tingency Plan						
	SCP submitted ar	nd approved - no revision	required o	or proposed			•	
	Additional Det	ails:						_
Revisions to	the Abandon	ment and Restorat	ion Plan					
		ed and approved - no rev		ed or proposed			•	
	Additional Det	ails:						٦
								_
Progressive		Work Undertaken ails (i.e., work comp	leted and	d future work	s propose	ed)		
	activities. The abandoned contents A	nree sites that neede ere is a site on top core racks, empty ba At the airstrip, there site there were emp	of one of the of the of the one of the order	the ore bodie other miscel oty barrels, s	es where to laneous p crap meta	there were pieces of h al and righ	e neavy It near the	
Results of th	e Monitoring	Program including	•					
					conds of	latitude a	nd longitu ▼	ıde) of
							_	Jide) of

Re	esults of any additional sampling and/or analysis that was requested by an Inspector
No	additional sampling requested by an Inspector or the Board
Ad	dditional Details: (date of request, analysis of results, data attached, etc)
Any other detail being reported.	ls on water use or waste disposal requested by the Board by November 1 of the year
No	additional sampling requested by an Inspector or the Board
Ad	dditional Details: (Attached or provided below)
	or follow-up actions on inspection/compliance reports
Ins	spection Report received by the Licensee (Date):
Ad	dditional Details: (Dates of Report, Follow-up by the Licensee)
Th	spection: September 27, 2006. Report filed: October 4, 2006 by INAC. e main issues and recommendations were: lo spill kits.
Any additional	comments or information for the Board to consider
Ple	ease see attached report.
Date Submitted Submitted/Prep Contact Informa	ared by: Candace Ramcharan

GPS Coordinates for water sources utilized

		Latitude			Longitude		
Source Description	o Deg	Min	Sec.	o Deg	Min	Sec.	
Camp domestic source	68	27	39.31	82	38	42.26	
Drilling source 1	68	26	2.36	82	47	7.11	
Drilling source 2	68	26	16.03	82	46	53.75	
Drilling source 3	68	25	49.39	82	47	17.82	

GPS Locations of areas of waste disposal

Location Description (type)	Latitude			Longitude		
	o Deg	, Min	, Sec	o Deg	Min	, Sec
Camp sump	68	27	34.12	82	38	36.96