

NWB Annual Report

Year being reported: 2009

License No: 2BE-RBP0811

Issued Date: October 31, 2008

Expiry Date: October 31, 2011

Project Name: Roche Bay Magnetite Project

Licensee: Advanced Explorations Inc./Roche Bay plc

Mailing Address: 50 Richmond Street East, Suite 300  
Toronto, Ontario M5C 1N7

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (\*optional):

Licence Requirements: the licensee must provide the following information in accordance with

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s): Water obtained with a pump and hose from locations provided.

Water Quantity:

10/day	Quantity Allowable Domestic (cu.m)
0/day	Actual Quantity Used Domestic (cu.m)
510/day	Quantity Allowable Drilling (cu.m)
0/day	Total Quantity Used Drilling (cu.m)

- Waste Management and/or Disposal
- ☒ Solid Waste Disposal
  - ☒ Sewage
  - ☒ Drill Waste
  - ☒ Greywater
  - ☐ Hazardous
  - ☐ Other:

Additional Details:

NO WATER USED OR WASTE GENERATED IN 2009

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:

Date of Spill:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

Please refer to attached Spill Contingency Plan

Revisions to the Abandonment and Restoration Plan

Additional Details:

Please refer to attached A and R Plan

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)  
Please refer to attached A & R Plan

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date):

Additional Details: (Dates of Report, Follow-up by the Licensee)

Water Use Inspection Report dated: July 19, 2009 (see attached report). No water was used in 2009, as the Roche Bay project was put on hold for the year. The inspector had some concerns with the fuel storage which were corrected, as documented, by his letter dated October 7, 2009 (see attached letter).

Any additional comments or information for the Board to consider

Date Submitted:  
Submitted/Prepared by:  
Contact Information:

March 23, 2010
Gary Williams
Tel: 416-203-0057 ext. 224
Fax: 416-203-0059
email: <a href="mailto:gary@advanced-exploration.com">gary@advanced-exploration.com</a>