

NWB Annual Report**Year being reported:**

License No: NWB2REG0406 Issued Date: August 5, 2004
 Expiry Date: July 31, 2006

Project Name: *Regan Lake***Licensee:** *Strongbow Exploration Inc.***Mailing Address:** *800-625 Howe Street
Vancouver, BC
V6C 2T6***Name of Company filing Annual Report** (if different from Name of Licensee please clarify relationship between the two entities, if applicable):*Strongbow Exploration Inc.***General Background Information on the Project** (*optional):

A 5 person camp was established at 65° 07' 39" N, 107° 50' 05" W, for a period of 8 days (July 11 to July 18, 2005). Activities included mapping, prospecting and soil sampling. The fly camp consisted of 5 small pup tents and one 12' x 14' Weatherhaven. No structures or wooden floors were constructed.

Licence Requirements: the licensee must provide the following information in accordance with

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	<u>Lake Beside Camp</u>	
Water Quantity:	<u>10 cu.m/day</u>	Quantity Allowable Domestic (cu.m)
	<u>0.4/day</u>	Actual Quantity Used Domestic (cu.m)
	<u>50 cu.m/day</u>	Quantity Allowable Drilling (cu.m)
	<u>N/A</u>	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

Water was handed by pails from an informally named Pita Lake. Sewage was disposed of and buried in small pits near the camp. Greywater was disposed of in natural depressions near camp. Combustable garbage was generally incinerated. All non-combustible and unburned garbage was flown out upon demobilization for appropriate disposal in Yellowknife. No diesel fuel was utilized at this site and only a couple of drums of Jet B (205 liters each) were used at the camp for helicopter support. All waste material, fuel drums and camp material were removed from the site upon demobilization.

Additional Details: *N/A*

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

N/A

Revisions to the Spill Contingency Plan

Additional Details: N/A

Revisions to the Abandonment and Restoration Plan

Additional Details: N/A

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Mapping, soil sampling and prospecting were completed in 2005. A diamond drill program may be completed in 2006 or 2007 but the scope and timing of this program has yet to be determined.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Pita Lake 65° 07' 38" N, 107° 50' 4.5"
 Additional Details:

N/A

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Greywater : 65° 07' 39" N, 107° 50' 7.8" (disposed of in a ground depression near camp) Sewage:
No locations available (buried in pits near camp)

Additional Details:

N/A

Results of any additional sampling and/or analysis that was requested by an Inspector

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Additional Details: (Attached or provided below)

Correspondence was received from the Nunavut Water Board dated October 21, 2005 acknowledging receipt of the 2004 Annual Report for activities conducted under NWB2REG0406 and requesting clarification of the following:

- 1) *Total Water use amount recorded and reported in cubic meters : Camp Use 14.45 cu.m
Drill Use 40.0 cu.m*
- 2) *Site Photographs with documentation detailing the Water Supply Facilities, Waste Disposal Facilities, and general site : A ten hole diamond drilling program was conducted between August 15, 2004 and September 27, 2004. Drill cuttings were settled out in natural depressions within 50m of the drill site locations provided below. More exact locations are not available and pictures are not available.*

65° 19' 24" N and 107° 37' 06" W
 65° 19' 27" N and 107° 37' 12" W
 65° 19' 29" N and 107° 37' 16" W
 65° 19' 28" N and 107° 37' 35" W
 65° 19' 28" N and 107° 37' 35" W
 65° 19' 29" N and 107° 37' 38" W
 65° 19' 28" N and 107° 37' 35" W
 65° 19' 29" N and 107° 37' 36" W
 65° 19' 26" N and 107° 37' 22" W
 65° 19' 27" N and 107° 37' 00" W

Attached please find 3 photographs of Strongbow Exploration Inc.'s Musk Camp from the 2004 exploration season which includes notations identifying the water supply/pumping station as requested.

Any responses or follow-up actions on inspection/compliance reports

Additional Details: (Dates of Report, Follow-up by the Licensee)

N/A

Any additional comments or information for the Board to consider

Attached please find 2 general site photographs of the Regan Lake Fly Camp taken during the 2005

exploration season

Date Submitted:	March 27, 2005						
Submitted/Prepared by:	Strongbow Exploration Inc.						
Contact Information:	<table border="1"> <tr> <td>Tel:</td> <td>604-668-8355</td> </tr> <tr> <td>Fax:</td> <td>604-668-8366</td> </tr> <tr> <td>email:</td> <td>nwestcott@strongbowexploration.com</td> </tr> </table>	Tel:	604-668-8355	Fax:	604-668-8366	email:	nwestcott@strongbowexploration.com
Tel:	604-668-8355						
Fax:	604-668-8366						
email:	nwestcott@strongbowexploration.com						