


APPENDIX 5


August 2002 Site Inspection

- 5.A.1: THE KIGGAVIK CAMP
- 5.A.2: THE KIGGAVIK CORE RACKS
- 5.A.3: THE KIGGAVIK TRENCHES
- 5.A.4: SOME of the KIGGAVIK DRILL SITES
- 5.A.5: THE ANDREW LAKE SITE
- 5.A.6: THE ANDREW LAKE OREBODY



5.A.1: THE KIGGAVIK CAMP

August 8th, 2002.



#4752: looking W- NW



#4751: looking N



#4750: looking NE




#4749: looking E

#4748: looking NE



#4753: looking S-SE






#4797: from the helicopter landing pad, looking East; kitchen/dining.




#4829: the showers /dry building



#4826: looking South from the
Kitchen; 2 personal cabins

**#2642: from the showers / dry building looking
equipment, office and personal cabins.**



**#2643: from the showers /dry
looking towards the kitchen**







5.A.2: THE KIGGAVIK CORE RACKS

August 8th, 2002



#2645: view of some core racks

#2647: core racks inspection with also P Putumiragtuq & T Kudloo.





Views of core racks requesting attention




5.A.3: THE KIGGAVIK TRENCHES

August 8th, 2002

#2368: M van Rooy; T Kudloo and L Manzo.





#2631: checking instruments before inspection. D. Spelay, L. Manzo & C. Gunning.

#2637: by a trench: M van Rooy, T Kudloo, L Manzo, K Wheatley and D Spelay; some drilling pads are visible in the background.



#4776: the larger trench



#4775: the smaller trench, with some waste gathered during that trip






Other views of the trenches




#2630:m the larger trench with C Maloney



#4757: other view of the larger trench; some vegetation took
already over




**#2633: Scintillometer reading >15,000cps
on debris coming from the trench**



#2635: close up of uranium oxides (yellow colour) coating metaquartzites





#4745: aerial view of the trenches located on the northern edge of a naturally highly radioactive area; there is also the exploration tools left (right hand lower corner) from a previous exploration campaign



#4762: detailed view of the above picture



#4746: area of natural outcrops north of the main trench and drilling sites

5.A.4: SOME OF THE KIGGAVIK DRILL SITES

August 8th, 2002

#4761: protruding steel casing to be cut and disposed off



#4765: view of the westernmost area drilled in relation with the Kiggavik orebodies





Protruding steel casing to be cut and disposed off





#4766

Protruding steel casing to be cut and disposed off, together with pail debris



#4770



Other drill sites to be attended; the trenches are visible on the lower picture



#4769: naturally, but not radioactive, outcropping area

