

NWB Annual Report

Year being reported: 2009



License No: 2BE-TAH0611 **Issued Date:** April 20, 2006
Expiry Date: March 31, 2011

Project Name: Victoria Island Project

Licensee: Diamonds North Resources Ltd.

Mailing Address: 510-510 Burrard Street
 Vancouver, B.C.
 V6C 3A8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

N.A.

General Background Information on the Project (*optional):

Diamonds North and partner Teck Cominco conducted both regional and detailed style explorations programs on Victoria Island from May to September, 2005. These programs consisted of till sampling, airborne magnetic surveying, ground geophysical surveying, prospecting and diamond drilling. Early in 2006 Teck Cominco decided not to continue with their option agreement on this project. No field work has been conducted on the project since 2006. In 2008 a small program of reducing claim sizes and surveying of the said claims was conducted during a 10 day period in August. This program involved 6 people. No work was conducted on the property in 2009.

Licence Requirements: the licensee must provide the following information in accordance with

Part B



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Tuktu river		
Water Quantity:	5 cu. m daily	Quantity Allowable Domestic (cu.m)	
	0	Actual Quantity Used Domestic (cu.m)	
	40 cu. m daily	Quantity Allowable Drilling (cu.m)	
	0 cu. m daily	Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

☐ Solid Waste Disposal

☐ Sewage

- ☐ Drill Waste
☐ Greywater
☐ Hazardous
☒ Other:

No work undertaken in 2009.

Additional Details:

Sewage: Contained in latrine pit and treated with lime. Pits backfilled at end of program.
Greywater: Collected in natural depression at least 30 metres from the the high water mark of any waterbody in an area where no direct flow into a waterbody was possible.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: N.A. (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

N.A.

Revisions to the Abandonment and Restoration Plan

Additional Details:

N.A.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

All pits, sumps and latrines have been backfilled. All garbage, empty fuel drums etc. have been removed and backhauled to Cambridge Bay for disposal. No contamination cleanup has occurred as no spills have occurred. The wooden structures that form the campsite have been secured and remain for future work programs. All garbage has been removed from site. Water pumps have been drained and stored in the secured dry tent along with any oils or additives. An inventory of the fuel cache at camp has been made.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below



Additional Details:

Domestic water: Tuktu River = 70° 48' 28" 109° 10' 04"
Note that no water was used in 2009.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below



Additional Details:

Greywater: 70° 48' 32" 109° 10' 55"
Latrine: 70° 48' 34" 109° 10' 38".
These areas were not utilized in 2009 as no work was undertaken.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

N.A.

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC



Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:
Submitted/Prepared by:
Contact Information:

Nov. 23rd, 2009
Graham Gill
Tel: 604 689 2010
Fax: 604 484 7143
email: ggill@diamondsnorthresources.com