AANDC Nunavut Regional Office Field Operations Unit P.O. Box 100, Iqaluit, Nunavut, X0A 0H0

Sent via E-mail CTDM #655150

Monday, April 16, 2013

Phyllis Beaulieu Manager of Licensing Nunavut Water Board P.O. Box 119 Gjoa Haven, NU X0B 1J0

Email: licensing@nunavutwaterboard.org

Re: 2012 Lands Inspection Report of 2BE-WLS0406 Strongbow Exploration LUP # N2004C0021

Phyllis,

Further to a request by Strong bow Resources for cancellation of the "Whales Island Project" Water license located in the Qikiqtani Region.

On August 5th, 2012, an AANDC Inspector conducted an inspection of the camp site and recommended that, based on the observations collected on site during the inspection, the site had been found reclaimed and that no waste remained on site.

A copy of this Inspection Report and associated photos has been attached to this letter for your review.

After a review of this report and by copy of this letter it is the recommendation of the Field Operations Section-AANDC, that this file may be approved for closure/cancellation by the Nunavut Water Board.

Should you have any concerns with respect to this information please feel free to contact this office with any questions you may have.

Thank you,

Manager - Field Operations

AANDC Nunavut Region, Igaluit

Cc: Murray Ball, Manager Waters – AANDC

Attached; WRO Field Inspection Report and photos

Date: August 5,2012	Licensee Rep. (Name/Title): None		
Licensee: Strongbow Ex	cploration Inc.	Licence No: 2BE-WLS0406	

Comments:

Camp is closed and area reclaimed. It appears the camp tent platforms were burned in place and remaining garbage hauled out. Some melted plastics were found in the ash at the site that should not have been burned but removed.

WATER SUPPLY

Source(s): None	Quantity used: None
Owner:/Operator:	

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Intake Facilities:	Storage Structure: I	Treatment Sys:	Chemical Storage:
Flow Meas. Device:	Conveyance Lines:	Pumping Stations:	Screen:

Comments: Camp Closed

WASTE DISPOSAL

Sewage:

	(, , , , , , , , , , , , , , , , , , ,		
Natural Water Body:	Continuous Discharge (land or water):		
Seasonal Discharge:	Wetlands Treatment:	Trench	

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

(Prim./Sec/Ter.):

Discharge Quality:	Decant Structure:	Erosion:
Discharge Meas. Device:	Dyke Inspection:	Seepages:
Dams, Dykes:	Freeboard:	Spills:
Construction:	O&M Plan:	A&R Plan:
Periods of Discharge: .	Effluent Discharge Rate:	

Comments: None, Camp Closed

SOLID WASTE MANAGEMENT AREAS: None

Landfill:	Burn & Landfill:	Other:	
		Oulei.	

Comments: It appears any remaining solid waste was hauled out by the Iciensee upon closure of the program.

Waste Oil Storage: None found on site.

FUEL STORAGE:

None

Owner/Operator:

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners:	Water within Berms:	Evidence of Leaks:
Drainage Pipes:	Pump Station & Catchment	s Berm:
Pipeline Condition:	Condition of Tanks:	

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collec	ted	Owner /Oper	rator:
None		INAC	
Signs Posted	SNP:		Warning:
Records & Rep	orting:		
Geotechnical In	spection:		

NON-COMPLIANCE OF ACT OR LICENCE:

None.

- Project has been closed by the licensee.
- A review of the file indicates that the Land Use Permit (N2004C0021) has been closed.
- The site appears to have had the tent platforms burned and all garbage hauled off site.
- Noted on site were two stacks of drill core.
- Some melted plastic remained in the ash left on site.
- Site is recommended for closure by the Inspector.

A.Keim	Sent by E-mail (Original signed and on
Inspector's Name	Inspector's Signature
None on site	
Representative Name	Representative Signature



Remains of one tent platform




Core boxes stacked in back ground August 5th, 2012.



Remains of second tent platform Airstrip in back ground August 5th, 2012.



Melted plastic found in ask from tent platforms (hauled out by inspector) August 5 2012



Site found on August 5, 2012