



INDUSTRIAL WATER USE INSPECTION REPORT

DATE: July 14/04 COMPANY REP.: Dave Stewart / Kirk Keller
LICENSEE: ~~Scot Stewart~~ Warden Resource Inc. LICENCE #: ~~NW26444~~ NWB1410008

WATER SUPPLY

Source: West Lake Quantity Used: 2000 gal / 1.5 days Meter Rdg.: NA

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Intake Facilities A Storage Structures A Treatment Systems A Recycling NA
Flow Meas. Device NA Conveyance Lines A Pumping Stations NA Modifications A

Comments: Water use not to exceed 100m³/day. Water use is 2000 gal every 1.5 days
West Lake is water supply. Maintenance underway to repair intake at West Lake. Some
oil spilled above the generator. This needs to be cleaned up. Need a screen on the intake pipe
and it needs to be > 50m from shore.

WASTE DISPOSAL

Tailings: Tailings Pond ☐ Natural Lake ☐ Underground ☐

Sewage: Sewage Treat. System ☐ Tailings Pond ☐ Natural Water Body ☐
Continuous Discharge ☐ Inter. Dischg. ☐

Solid Waste: Open Dump ☐ Landfill ☐ Burn & Bury ☐ Underground ☐

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Discharge Quality NA Conveyance Lines NA Disch. Meas. Dev. NA Freeboard A
Decant Structures NA Pond Treatment NA Dams, Dykes NA Seepages NA
Dyke Inspections NA Runoff Diversion NA Erosion NA Spills A

Effluent Discharge Rate: _____ Samples Collected: _____

Comments: Spill contingency plan? Sumps? The bundle waste is buried with metal
waste cut up & shipped south. Food waste is incinerated daily ~ apparently operator will ensure
goes through an ABC before being discharged to East Lake.

GENERAL CONDITIONS

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Ore & Waste Rock Stockpiles A Records & Reporting A Surv. Net. Prog. U
Geotechnical Inspection NA Posting, Signage U Contingency Plan A
Restoration Activities NA New Construction NA Fuel Storage A
Mine Water Discharge NA Chemical Storage NA Annual Report NA

Comments: The fuel storage areas Tank farm & day tank are well bermed and
apparently well maintained with an exposed liner.

Violations of Act or Licence: There were no apparent violations of the act or
licence however a monitoring program, with appropriate signage needs
to be implemented. Also the small spill around camp and at West Lake need to be cleaned.

General Comments: Potable water is treated with UV and filtered before use. It
appears to be well maintained however the water quality is not yet
monitored. Outgoing water quality needs to be monitored to ensure the
safety of the potable water.

Page 2 attached ☐ Yes ☐ No

Licensee Representative's Title
Senior Geologist

Licensee Representative's Signature
[Signature]

INTERNAL	
PC	clp
MA	
FO	
LA	
BS	
ST	

Inspector's Name
Scott Stewart

Inspector's Signature
[Signature]

