



July 5 2013 Inspection of 2BM-ULU0914



Figure 1. Ulu Mine site on July 5, 2013.



Figure 2. Water intake at West Lake has been removed from the lake.



Figure 3. Barrels remain on the rock pad. These are to be moved to the hazardous waste storage area.



Figure 4. Four barrels of sewage remain from 2012. These are to be backhauled.



Figure 5. Many barrels have been moved into the tank farm berm and the lined storage area beside it.



Figure 6. Spills are visible throughout the site that were not addressed as per the spill contingency plan.



Figure 7. A recent leak at the storage area.



Figure 8. A leaking barrel at the airstrip, beside the berm with MMG's fuel.



Figure 9. The berm containing MMG's fuel is ripped.