



PHOTOS OF INSPECTION: JULY 12 2014



Figure 1. Ulu site; seen from the air July 12 2014.



Figure 2. Barrels of waste noted on Mine Waste Pad.



Figure 3. Barrels of waste on Mine Waste Pad. Staining noted.



Figure 4. Barrels at Mine Waste Pad. Hazardous waste noted, with no containment.



Figure 5. Contents of barrels at Mine Waste Pad consistent with hazardous waste.



Figure 6. Photo of helipad area and waste piles, facing west.



Figure 7. Barrels of unknown content found in waste piles to east of helipad.



Figure 8. Staining noted from barrels to east of helipad.



Figure 9. Fuel/barrel storage area to east of tank farm. Note staining running downhill from the lined area.



Figure 10. Several stains noted in the barrel storage area.



Figure 11. Airstrip apron. Yellow berm contains waste for backhaul. Other visible barrels are empty.



Figure 12. Yellow berm contains waste, including a punctured barrel.



Figure 13. Opposite airstrip apron has full barrels of fuel, with no containment.



Figure 14. Caps on indicate full barrels.



Figure 15. Barrels noted on pallets (without containment) on the roadside near the airstrip.