



Suite 1125, 595 Howe Street,
Vancouver, BC V6C 2T5
CANADA
Tel: +1.778.379.1433
Fax: +1.778.379.1434

20 August 2020

Richard Dwyer
Manager of Licencing
Nunavut Water Board
PO Box 119
Gjoa Haven, NU
X0B 1J0

Dear Mr. Dwyer,

Re. 2BM-ULU2030 Part D Item 15 – Geotechnical Inspection

Further to Part D Item 15 of 2BM-ULU2030, Blue Star Gold Corp. (Blue Star) wishes to confirm with the Nunavut Water Board requirements pertaining to the 2020 Geotechnical Inspection.

Blue Star understands that this condition is intended to apply to inspection of major infrastructure and/or earth works. Activities on site in 2020 are limited to camp management, mineral exploration, progressive reclamation, and waste segregation, staging and backhaul; no significant mine or construction-related operations will be undertaken on site in 2020. Accordingly, Blue Star understands that a Geotechnical Inspection will not be necessary in 2020.

Blue Star respectfully requests that the Nunavut Water Board provide a response, confirming this understanding.

Should you have any questions about the project or this matter, please contact Sharleen Hamm at 604.996.1110 or Sharleen.hamm@bluestargold.ca.

Regards,

Peter Kuhn
General Manager
Blue Star Gold Corp.
Peter.kuhn@bluestargold.ca
778.379.1433

Encl.

cc. D. Donald, Nunavut Water Board
W. Kuliktana, Kitikmeot Inuit Association
B. Campbell, Crown-Indigenous Relations and Northern Affairs