



P.O. Box 119  
GJOA HAVEN, NU X0B 1J0  
TEL: (867) 360-6338  
FAX: (867) 360-6369

NUNAVUT WATER BOARD  
NUNAVUT IMALIRIYIN KATIMAYINGI

---

May 31<sup>st</sup>, 2006

*File:* NWB1ULU0008 (D9)  
*Fax:* 807.345.0284

David Stevenson  
Project Manager, Ulu  
Wolfen Resources  
*Email:* [dave.stevenson@wolfdenresources.com](mailto:dave.stevenson@wolfdenresources.com)

**Subject: NWB review of submitted Geotechnical Inspection Report Ulu Mine Site**

Dear Mr. Stevenson:

The Nunavut Water Board (NWB) has reviewed the geotechnical inspection report completed by BGC Engineering Inc. (BGC), on behalf of Wolfden Resources Inc. (Wolfden). This submitted report was received September 16<sup>th</sup>, 2005 and is pursuant to **Part D, Item 9** of water licence **NWB1ULU0008**. As per **Part D, Item 9**, Wolfden is to prepare an implementation plan that appropriately addresses BGC's recommendations. The covering letter, accompanying the submitted report, simply lists that all report recommendations have been complied with. The NWB requests proper documentation and photographic record capturing how the remedial was completed for each and every BGC recommendation listed on report pages 6 through 11. The NWB also requests a classification of the geosynthetic membrane liner installed at the inspected facilities. The NWB requests that this additional information be provided no later than sixty (60) days following the date of this letter.

Sufficient detail and an avoidance of ambiguity should be followed in submitting response materials. If you require assistance whatsoever please feel free to contact the undersigned at (867) 360-6338 or [tech1@nwb.nunavut.ca](mailto:tech1@nwb.nunavut.ca).

Sincerely,

*Original signed by:*

Joe Murdock  
Technical Advisor