



3 December 2009

Ms. Phyllis Beaulieu  
Manager of Licensing  
Nunavut Water Board  
P.O. Box 119  
Gjoa Haven, Nunavut  
X0B 1J0

Dear Phyllis

**ANNUAL GEOTECHNICAL INSPECTION**

**VARIOUS EARTH STRUCTURES**

**ULU ADVANCED EXPLORATION SITE, WATER LICENSE # ULU-2BM-ULU0914**

Please find enclosed a copy of the 2009 geotechnical inspection report for the Various Earth Structures at the Ulu advanced exploration site, Water Licence ULU-2BM-ULU0914, dated December 1, 2009. The recommendations in the report relate to minor repair and maintenance items for the secondary containment berms and liners at various fuel and lubricant storage and handling facilities at the site as well as repairs to the synthetic liner for the mine sump. The noted repairs to the secondary containment liners will be made while we are operating at our nearby High Lake camp in the summer of 2010. The repairs to the mine sump will be made prior to the resumption of underground work, at an undetermined time in the future, as this component of the site is not in commission unless water is pumped from underground.

We trust the above provides the information you require with respect to the geotechnical inspection for 2009 at the Ulu Advanced Exploration Site. If you have any questions, please do not hesitate to contact me.

Yours truly

A handwritten signature in black ink that reads 'Andrew Mitchell'.

**Andrew Mitchell**

Development Manager

T 807 346 1692  
F 807 345 0284  
E [andrew.mitchell@mmgrouppltd.com](mailto:andrew.mitchell@mmgrouppltd.com)  
M 807 251 6722

cc Ms. Dionne Filiatrault P. Eng. - Nunavut Water Board  
Dave Honstein - Nunavut Water Board  
Ms. Melissa Joy, INAC  
Mr. Chad Harden - Environment Canada  
Martin McFarlane - MMG Resources

enc 2009 Geotechnical Inspection Report