



WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee	Licensee Representative
Hamlet of Arviat	Steve England
Licence No. / Expiry	Representative's Title
3AM-ARV1016	Senior Administrative Officer
Land / Other Authorizations	Land / Other Authorizations
Date of Inspection	Inspector
20/07/2015	Atuat Shouldice
Activities Inspected	
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
<input checked="" type="checkbox"/> Other: Deposit of Waste	<input type="checkbox"/> Construction
	<input type="checkbox"/> Reclamation
	<input checked="" type="checkbox"/> Fuel Storage
	<input checked="" type="checkbox"/> Other:Water use

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected
Water Use	Condition	Comment	Site Conditions	Condition	Comment
Intake/Screen	A		Water Management Structures	A	
Flow Measure. Device	C	1	Culverts / Bridges	A	
Source:	A		Drainage	A	
Water Use:	A		Erosion / Sediment	A	
Recirculation ( y /n)	N		Mitigation Measures	A	
			Reclamation Activities	A	3
			Materials Storage	A	
			Signage	A	
Waste Disposal					
Waste Water	A				
Solid Waste	A		Monitoring		
Hazardous Waste	A	2	Sample Collection / Analysis	A	
*The number in the comments field will correspond with specific comments provided below.					
Samples taken by Inspector:			Location(s): Hamlet of Arviat		
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

SECTION 1	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
A compliance inspection was conducted on July 20 <sup>th</sup> 2015 of water licence 3AM-ARV1016.			
SECTION 2	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
Water Use: 1 Water meter was installed at source to measure total amount of water being pumped in to water lagoon, during pumping small piece of debris made it passed filter and damaged water meter. Since incident water meter has been repaired.			
Waste Disposal:2 Waste oil being generated in community is being burnt in a waste oil burner.			
Site Conditions:3 Contractors hired in previous year to remove hazardous waste from old equipment and back haul to approved waste disposal facility.			
Haz/Mat Management:4 Hazardous waste is being properly stored and segregated from landfill.			
SECTION 3	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input type="checkbox"/> Action Required (s. __)
No concerns with site. Related to the use of water and the deposit of waste the Hamlet of Arviat has been following the goal set in the Water licence working compliance group.			

Licensee or Representative	Inspector's Name
	Atuat Shouldice
Signature	Signature
Date	Date
	10/12/2015

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input type="checkbox"/> No
------------------	--	--