



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee Hamlet of Arviat	Licensee Representative Steve England
Licence No. / Expiry 3AM-ARV1016	Representative's Title Senior Administrative Officer
Land / Other Authorizations	Land / Other Authorizations --
Date of Inspection August 9 th 2017	Inspector Atuat Shouldice
Activities Inspected <input type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input checked="" type="checkbox"/> Other: Municipality <input type="checkbox"/> Other:	

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
-----------	--	---	--

Summary

On August 9th, 2017 Indigenous and Northern Affairs Canada's Water Resource Officer, Atuat Shouldice completed an annual Community inspection of the hamlet of Arviat permit 3AM-ARV1016. The inspection was conducted in the presence of Megan Lusty, Municipal Planning Engineer and Steve England Senior Administrative Office. During the writing of this report the Hamlet of Arviat was in the process of renewing their water licence.

SECTION 2	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s. __)
-----------	--	---	--

Observations

LANDFILL

The landfill in Arviat is very organized and well maintained; signage is posted to segregate Hazardous waste from entering the landfill. Recycling is an active project, segregating lumber and building materials to be reused.

WASTE METAL DUMP

The Hamlet of Arviat recently purchased a crusher to shred bulk items. During the inspection, the hamlet had on-going program to depollute automotive vehicles and recreational vehicles. During the course of the inspection, no waste was seen leaving the landfill and metal dump sites.

Hazardous Waste

Hazardous waste is regularly collect and stored in seacans. The Hamlet of Arivat runs programs and informs community on how hazardous waste should be store and places before collected.

SEWAGE DISPOSAL

The sewage lagoon was inspected during the site visit. The lagoon appeared to be in good repair and adequate freeboard was observed. Sewage samples taken by the Hamlet indicate that effluent was within water license criteria.

WATER USE

The drinking water pumphouse was visited during the inspection and water use records were made available for review. The water is being recorded as required at wolf creek and also by truck loads filled from resolver. No water license compliance issues were noted.

SECTION 3	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input checked="" type="checkbox"/> Action Required (s.3)
-----------	---	--	---

The Hamlet of Arviat is currently using water without the authorization of a valid water licence. This is in contravention of the Nunavut Waters and Nunavut Surface Rights Tribunal Act, section 11. In order for Arviat to be authorized for their current activities they must hold a water licence for the use of water and deposit of waste. This includes the use of drinking water from Wolf Creek and the discharge of waste from the sewage lagoon. The Hamlet needs to continue demonstrating progress towards obtaining a water license.

Licensee or Representative	Inspector's Name WRO A Shouldice
Signature	Signature
Date	Date 4/19/2018

Office Use Only:	Follow-up report to be issued by Inspector	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
------------------	--	---