



WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Community and Government Services	Megan Lusty
Licence No. / Expiry	Representative's Title
3AM-GRA1624/ May 1st, 2024	Manager, Municipal Works
Land / Other Authorizations	Land / Other Authorizations
--	--
Date of Inspection	Inspector
August 11 th 2020	Atuat Shouldice
Activities Inspected	
<div><input type="checkbox"/> Camp<input type="checkbox"/> Drilling<input type="checkbox"/> Mining<input type="checkbox"/> Construction<input type="checkbox"/> Reclamation<input type="checkbox"/> Fuel Storage</div> <div><input type="checkbox"/> Roads/Hauling<input checked="" type="checkbox"/> Other: Waste Disposal Facility<input checked="" type="checkbox"/> Other: Water Treatment Facility</div>	

SECTION 1	<input checked="" type="checkbox"/> Comments (s. 1_)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
<div>Background</div> <p>On August 11th 2020, a regularly scheduled inspection was conducted of the Nunavut Water Board (NWB) water licence no. 3AM-GRA1624 issued to the Government of Nunavut, Community and Government Services (CGS) for the use of water related to the fresh water intake, re-supply line, Water Treatment Plant (WTP) and Sewage Treatment Facility (STF). The inspection was conducted to ensure compliance with applicable terms and conditions of the licence.</p> <div>Observation</div> <div><div>1. The 2019 Annual Report is available for review on the NWB’s website.</div><div>2. Fresh water is drawn from Nipisar Lake at monitoring station GRA-1.</div><div>3. The total water used in 2019 according Annual Report was 630,094 m³ which respected the annual allotment of 850,000 m³.</div><div>4. In 2019 a concern was noted at the Nipisar Lake, Water Intake regarding the fuel tank and line. The tank and line have since been replaced.</div><div>5. Sewage sludge is deposited at a rate of 1 cubic meter per week, into a designated area at the municipal Landfill.</div><div>6. All signage is posted as required by PART B item 5.</div></div>			
SECTION 2	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<div>Concerns related to Water Licence no. 3AM-GRA1624;</div> <div>— No concerns noted at this time.</div>			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required
<div>The Government of Nunavut continues to work towards improving the fresh water supply. An amendment has been recently submitted to the Nunavut Water Board to capture the increase fresh water intake from Landing Lake.</div>			

Licensee or Representative	Inspector's Name
Megan Lusty	Atuat Shouldice
Signature	Signature
	Sent Electronically
Date	Date
	December 10 th , 2020

CC:

Licensing Department, NWB
Justin Hack, Manager of Field Operations, CIRNAC
Megan Lusty, Municipal Works, CGS



PHOTO LOG			
Date:	Authorization Number:	Camera/Model:	Inspector
August 11th, 2020	3AM-GRA1624	Samsung S9	RMO Shouldice
Photo No.		Lat/Long (DD.MM.SS.SS, NAD83)	
Photo 1		With in municipality	
Description:			
Pump house with new fuel tank and fuel line.			





Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)
Photo 2	With in municipality
Description: Pump house with new fuel tank and fuel line.	





Relations Couronne-Autochtones
et Affaires du Nord Canada

Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)
Photo 3	With in municipality
Description: Pump log sheets in to Nipisar lake	

