

WATER USE INSPECTION REPORT

Date: July 21,2009	Licensee Rep. (Name/Title): Johhny Kubloo
Licensee: Municipality of Igloodik	Licence No.: 3BM-IGL0911

WATER SUPPLY

Source(s): Water Reservoir	Quantity used: Unknown / no records
Owner:/Operator: Municipality of Igloodik	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: A	Storage Structure: A	Treatment Systems: A	Chemical Storage: NI
Flow Meas. Device: U	Conveyance Lines: NI	Pumping Stations: A	Screen : NI

**Comments:** The Municipality has been provided a renewal/ extension license to allow the municipality the time necessary to come into compliance with the Terms and conditions contained within the License.

WASTE DISPOSAL

**Sewage:** Sewage Treatment System (Prim./Sec/Ter.):Primary

Natural Water Body: No	Continuous Discharge (land or water): NA		
Seasonal Discharge: Decant on-0going	Wetlands Treatment: None	Trench: None	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: U	Decant Structure: NA	Erosion: NI
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: U
Dams, Dykes: NA	Freeboard: A	Spills: NI
Construction: NA	O&M Plan: U (none submitted)	A&R Plan: U
Periods of Discharge: Con.	Effluent Discharge Rate: Unknown	

**Comments:** Sewage from the 5 cell lagoon is continuously seeping through the walls of the lagoons. Decant was on-going during the inspection. No notification to the Inspector was sent.

**Solid Waste:** Waste not segregated, Hazardous wastes noted in Municipal land fill.

**Owner/Operator:** Municipality of Igloodik

Landfill: U	Burn & Landfill: U	Other: Bulk metals area
-------------	--------------------	-------------------------

FUEL STORAGE: Not inspected.

**Waste Oil Storage:** None

**Owner/Operator:** Government of Nunavut

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: NI	Water within Berms: NI	Evidence of Leaks: NI
Drainage Pipes: NI	Pump Station & Catchments Berm: NI	
Pipeline Condition: NI	Condition of Tanks: NI	

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected		Owner /Operator: No samples from Municipality have been submitted	
2		INAC: Potable water source & Effluent discharge	
Signs Posted	SNP: none		Warning: 1 at Lagoon
Records & Reporting: No records of water usage, waste discharge.			
Geotechnical Inspection: N/A			

**Non-Compliance of Act or Licence:** The water reservoir and intake were in operation and well kept. The waste management area was un-segregated and hazardous wastes were noted. Seepages from the lagoon continue to flow down gradient to the ocean shoreline. The Municipality is reminded that the current license as issued contains a number of reporting and submission requirements that are necessary to ensure proper monitoring and compliance with the Act.

A.Keim

Inspector’s Name

Sent by E-mail

Inspector’s Signature