



SPILL REPORT

(Oil, Gas or Other Materials, i.e. Hazardous Chemicals, etc.)

24-Hour Report Line
Phone (403) 920-8130

91-105

Report Date A June 20/91		Date and Time of Spill if Known Spill started sometime in winter, noticed June 19/91	
Location and Map Coordinates (if known) and Direction if Moving B - Hamlet of Igloodik house number #38			
Party Responsible C - Housing Association			
Product Spilled and Estimated Quantities (Provide Metric Volumes/Weights if Possible) D - P50 Heating oil 1 drop every 5 sec. } tenant noticed drip when snow started to melt apr 3 mos.			
Cause of Spill E - Oil tank line leak under the house			
Is Spill Terminated or <u>Continuing</u> F - Continuing			
Extent of Contaminated Area G - Under the house, hard to determine extent because of ice under the house.			
Factors Affecting Spill or Recovery - Temperature, Wind, Snow, Ice, Terrain, Buildings, etc. H - ice under house - oil is almost impossible to get to.			
Containment - Naturally, Booms, Dykes or Other, No Containment I - nil			
Action, if any, Taken or Proposed to Contain, Recover, Clean-up or Dispose J - Housing Association proposed to repair.			
Do You Require Assistance K - Yes		If so, What Form - Finance by-pass pipe needs to be repaired.	
Hazard to Persons or Property or Environment - Fire, Drinking Water, Threat to Fish or Wildlife L - Fire hazard to building.			
Comments and/or Recommendations M - When Housing Association was notified they had already been aware of it for sometime before hand. LEAD: GNWT SIGN: MINOR NAP D.O. : BAFFIN			
Reported by Thro. Kummag		Position, Employer, Location Ren Res - Igloodik.	
Reported to Laurie		Telephone 819-934-8999	
		Telephone 403-920-8130	