



SPILL REPORT

(Oil, Gas or Other Materials, i.e. Hazardous Chemicals, etc.)

24-Hour Report Line
Phone (403) 920-8130

File #: 0571

91-106

A	Report Date June 20/91	Date and Time of Spill if Known Spill started in the winter Sometime
B	Location and Map Coordinates (if known) and Direction if Moving - Hamlet of Igloodik vacant house # 1114	
C	Party Responsible - Housing Association	
D	Product Spilled and Estimated Quantities (Provide Metric Volumes/Weights if Possible) - P50 Heating Oil 1 drop every 3 seconds. probably leaking all winter.	
E	Cause of Spill - Oil tank line has leak	
F	Is Spill Terminated or <u>Continuing</u> Continuing	
G	Extent of Contaminated Area - under tank and house	
H	Factors Affecting Spill or Recovery - Temperature, Wind, Snow, Ice, Terrain, Buildings, etc. - Ice near house, and house is at ground level	
I	Containment - Naturally, Booms, Dykes or Other, No Containment - nil	
J	Action, if any, Taken or Proposed to Contain, Recover, Clean-up or Dispose - Housing Association has proposed to repair pipe	
K	Do You Require Assistance - Yes	If so, What Form - to remove contaminated gravel & mud
L	Hazard to Persons or Property or Environment - Fire, Drinking Water, Threat to Fish or Wildlife - Fire hazard to vacant building	
M	Comments and/or Recommendations - gravel under house is almost impossible to get to because building is only about 3 inches above ground level. LEAD: G N W T SIGN: MINOR NAP D.O.: BAFFIN	
Reported by Thao Kunnag		Position, Employer, Location Ren Res Igloodik
Reported to Laurie		Telephone 819-934-8999
		Telephone 403-920-8130