



SPILL REPORT

(Oil, Gas or Other Materials, i.e. Hazardous Chemicals, etc.)

24-Hour Report Line

Phone (403) 920-8130

91-199

A	Report Date OCT. 15	Date and Time of Spill if Known OCT. 11, 1991
B	Location and Map Coordinates (if known) and Direction if Moving IGLOOLIK, CO-OP	
C	Party Responsible SAVIK, As we were the party pumping gas into tank	
D	Product Spilled and Estimated Quantities (Provide Metric Volumes/Weights if Possible) GAS	
E	Cause of Spill Tank Overflowed.	
F	Is Spill Terminated or Continuing TERMINATED.	
G	Extent of Contaminated Area 1 sq. meter.	
H	Factors Affecting Spill or Recovery - Temperature, Wind, Snow, Ice, Terrain, Buildings, etc. CUSTOMER ORDERED too much gas for tank capacity	
I	Containment - Naturally, Booms, Dykes or Other, No Containment ABSORBING Cloth shoveled + cleaned up.	
J	Action, if any, Taken or Proposed to Contain, Recover, Clean-up or Dispose Clean Up was done immediately.	
K	Do You Require Assistance NO	If so, What Form
L	Hazard to Persons or Property or Environment - Fire, Drinking Water, Threat to Fish or Wildlife NO.	
M	Comments and/or Recommendations SAVIK was asked to deliver a tank of gas to CO-OP. The tank ^{the CO-OP} was not empty, & it overflowed. The loss of gas was approximately 10-12 gal. It was cleaned up immediately by SAVIK. Lead: GNWT NAP District: BAFTEN Spill Significance: -MINOR	
Reported by Anastasio Gjorgiev		Position, Employer, Location Driver, Savik Enterprises
Reported to Rick Porter		Position, Employer, Location President, Savik Enterprises
		Telephone 1-819-934-8903
		Telephone 1-819-934-8903