



Department of Health & Social Services: Baffin

To:

SUBMITTED WATER SAMPLE RESULTS

The bacteriological water samples listed below were analyzed and the results are as indicated.

Location of Sample	Total Coliform	E. coli	Acceptable Yes/No	Comments
Raw water	3	0	yes	note - * Raw OK
Treated at Plant	0	0	yes	PR
Arena	0	0	yes	PR
Bikes/loop	0	0	yes	PR
House - 2711A	0	0	yes	PR
4014-12	0	0	yes	PR
4084	0	0	yes	PR
2604 D	0	0	yes	PR
2776	7	0	no	bathroom tap

Counts above zero require immediate re-sampling. If you have any problems or questions, please call or fax an Environmental Health Officer at the numbers listed above.

Regards,

Cc:

Philip Reeve

Environmental Health Officer



Department of Health & Social Services: Baffin

$\Delta C_{\text{H}_2O} \approx \frac{\Delta T}{T} \cdot C_p$

Okoa Kavamat Monakhikakvilikiot Olasilikiot

Ministère de la Santé et des Services Sociaux

P.O. Box 1000 STN 1046; 00006; C.P. 1000 STN 1046

Iqaluit, NU Δ⁹-Δ⁸, Δ⁹ X0A 0H0

Phone: 867-975-4800 Fax: 867-975-4833

To:

I gollwit

Date:

Feb 28/04

Sample Date:

Feb/2 7104

Lab Date:

65/27/04

SUBMITTED WATER SAMPLE RESULTS

The bacteriological water samples listed below were analyzed and the results are as indicated.

Location of Sample	Total Coliform	E. coli	Acceptable Yes/No	Comments
Raw water plant	0	0	Yes	PK1
Treated water plant	0	0	Yes	PK1
Quick stop	0	0	Yes	PK1
Truck #89	0	0	Yes	PK1
Truck #48	0	0	Yes	PK1
Truck #50	0	0	Yes	PK1
Truck #43	0	0	Yes	PK1
Now arena	0	0	Yes	PK1

Counts above zero require immediate re-sampling. If you have any problems or questions, please call or fax an Environmental Health Officer at the numbers listed above.

Regards,

Cc:

Philip Kozma.

ENTERED
4 MAR 24
[Signature]

Environmental Health Officer

