



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 08-12-2010	REPORT TIME 10:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR		REPORT NUMBER -
B	OCCURRENCE DATE: MONTH – DAY – YEAR 08-12-2010	OCCURRENCE TIME -15:30	<input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION House # 2523			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES MINUTES SECONDS		LONGITUDE DEGREES MINUTES SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Iqaluit. NU. X0A 0H0			
G	ANY CONTRACTOR INVOLVED Lawlor Mechanical	CONTRACTOR ADDRESS OR OFFICE LOCATION Box 11160 Iqaluit. NU. X0A 0H0			
H	PRODUCT SPILLED Heating Fuel	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 400 - 500 litres approx	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Heating Fuel Tank	SPILL CAUSE Sewage Truck backed into tank	AREA OF CONTAMINATION IN SQUARE METRES 8 sq. m.		
J	FACTORS AFFECTING SPILL OR RECOVERY seepage under home	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS At approximately 15:30 on Aug. 12 it was reported that sewage truck accidentally backed into a home heating fuel tank at House # 2523 in the City of Iqaluit. Bylaw and Nunatta Environmental were immediately called to the scene, where it was noted that approx. 400 - 500 litres of diesel fuel had leaked out of the tank. City equipment was called in to remove the fuel tank and stand from site and cleanup was started with City of Iqaluit equipment including a backhoe, loader, dump truck and several employees with shovels. The cleanup is ongoing, with all contaminated soil being hauled to Nunatta Environmental disposal yard. Upon satisfactory completion, Nunatta Environmental will take soil samples of area and re-assessment can be done. At present, there has been approximately 30 m.3 of soil removed from site and disposed of at Nunatta and manual cleanup is ongoing. Lawlor Mechanical was used to hook up a temporary home heating fuel supply tank until cleanup is complete.				
L	REPORTED TO SPILL LINE BY Frank Ford	POSITION PW. Superintendent	EMPLOYER City of Iqaluit	LOCATION CALLING FROM Iqaluit	TELEPHONE 867-979-5653
M	ANY ALTERNATE CONTACT Rob Hogan	POSITION Utilidor Forman	EMPLOYER City of Iqaluit	ALTERNATE CONTACT LOCATION Iqaluit	ALTERNATE TELEPHONE 867-222-2941
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					

