



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR February 1/2010	REPORT TIME 9:00 am	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR		REPORT NUMBER 10 - 024
B	OCCURRENCE DATE: MONTH – DAY – YEAR January 29/2010	OCCURRENCE TIME 7:04 pm	<input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) na	WATER LICENCE NUMBER (IF APPLICABLE) na			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION Lift Station #1 City of Iqaluit			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES na MINUTES na SECONDS na		LONGITUDE DEGREES na MINUTES na SECONDS na		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION P O Box 460 Iqaluit NU X0A 0H0			
G	ANY CONTRACTOR INVOLVED Nunatta Environmental	CONTRACTOR ADDRESS OR OFFICE LOCATION P O Box 267 Iqaluit N U X0A 0H0			
H	PRODUCT SPILLED fuel oil	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 500 liters est.	U.N. NUMBER un-1202		
	SECOND PRODUCT SPILLED (IF APPLICABLE) na	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES na	U.N. NUMBER na		
I	SPILL SOURCE Fuel Tank	SPILL CAUSE Valve Bonet	AREA OF CONTAMINATION IN SQUARE METRES 6 meters by 6 meters		
J	FACTORS AFFECTING SPILL OR RECOVERY see k	DESCRIBE ANY ASSISTANCE REQUIRED see k	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT see k		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS On January 29/2010 at 7:04 pm I received an alarm at Lift Station #1. The alarm was for low fuel. I arrived on site at 7:18 pm. I looked at the fuel tank located in the rear of the building and noticed the bonet of the valve wasn't there. The tank at that time was empty. I notified Frank Ford Ops Sup. Eepa Nauyuk gave me a hand and we fixed it immediately by replacing the vavle. We then notified Nuna Env. to clean the spill and they were there cleaning within the hour. Uqsuk was called out around 7:30 pm and they filled the tank half full so we could heat our building. Bylaw was also called in at that time. Any further questions please don't hesitate to call				
L	REPORTED TO SPILL LINE BY Robert Hoan	POSITION Utilidor Forman	EMPLOYER City of Iqaluit	LOCATION CALLING FROM 1554d	TELEPHONE 867-222-2941
M	ANY ALTERNATE CONTACT Frank Ford	POSITION Ops Sup.	EMPLOYER City of Iqaluit	ALTERNATE CONTACT LOCATION Fed Garade	ALTERNATE TELEPHONE 867-222-2965
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input checked="" type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY	Robert Eno		02/01/10 11:46		
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					