



NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

| | | | | | |
|--|--|--|---|---|---|
| A | REPORT DATE: MONTH – DAY – YEAR March 16, 2010 | REPORT TIME 4:45PM | <input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT | | REPORT NUMBER _____ |
| B | OCCURRENCE DATE: MONTH – DAY – YEAR March 15, 2010 | OCCURRENCE TIME 4:00PM | | | |
| C | LAND USE PERMIT NUMBER (IF APPLICABLE) | | WATER LICENCE NUMBER (IF APPLICABLE) | | |
| D | GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Manhole - 63B, 32B, 32A and Lift Station #2 | | REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN | | |
| E | LATITUDE DEGREES MINUTES SECONDS | | LONGITUDE DEGREES MINUTES SECONDS | | |
| F | RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit | RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO Box 460 Iqaluit, Nunavut X0A 0H0 | | | |
| G | ANY CONTRACTOR INVOLVED | CONTRACTOR ADDRESS OR OFFICE LOCATION | | | |
| H | PRODUCT SPILLED Sewage diluted with potable water | QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 5000 liters estimated | U.N. NUMBER | | |
| | SECOND PRODUCT SPILLED (IF APPLICABLE) | QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES | U.N. NUMBER | | |
| I | SPILL SOURCE Lift Station #2 | SPILL CAUSE Water Main Break | AREA OF CONTAMINATION IN SQUARE METRES 90 | | |
| J | FACTORS AFFECTING SPILL OR RECOVERY | DESCRIBE ANY ASSISTANCE REQUIRED | HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT | | |
| K | ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS On March 15, 2010, our utilidor foreman received a call from dispatch for a mechanical alarm at Sewage Lift Station #2. The foreman checked the adjacent AV and noticed it was full and overflowing. Sewage trucks and a cleanup crew started immediately, while that was taking place the utilidor foreman noticed that there was a water main break inside manhole 63A, causing an extreme amount of water flowing through the sewer lines to Lift Station #2. The spill is contained to snow and ice around the overflow from Lift Station #2. The cleanup is ongoing and the contaminated snow and ice is being deposited at the sewage lagoon. Once the water was shutdown the utilidor staff was able to identify the actual cause of the water main break and worked through the night to replace the faulty valve which caused the spill. | | | | |
| L | REPORTED TO SPILL LINE BY Rob Hogan | POSITION Utilidor Foreman | EMPLOYER City of Iqaluit | LOCATION CALLING FROM Iqaluit | TELEPHONE 867-222-2941 |
| M | ANY ALTERNATE CONTACT Paul Clow | POSITION Project Officer | EMPLOYER City of Iqaluit | ALTERNATE CONTACT Iqaluit LOCATION | ALTERNATE TELEPHONE 867-979-6363 |
| REPORT LINE USE ONLY | | | | | |
| N | RECEIVED AT SPILL LINE BY | POSITION STATION OPERATOR | EMPLOYER | LOCATION CALLED YELLOWKNIFE, NT | REPORT LINE NUMBER (867) 920-8130 |
| LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC | | | SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN | | FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED |
| AGENCY | | CONTACT NAME | CONTACT TIME | REMARKS | |
| LEAD AGENCY | | | | | |
| FIRST SUPPORT AGENCY | | | | | |
| SECOND SUPPORT AGENCY | | | | | |
| THIRD SUPPORT AGENCY | | | | | |