



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR April 01, 2010	REPORT TIME 12:00 P.M.	<input type="checkbox"/> ORIGINAL SPILL REPORT, OR		REPORT NUMBER 2010-083
B	OCCURRENCE DATE: MONTH – DAY – YEAR March 18, 2010	OCCURRENCE TIME 2:30 P.M.	<input checked="" type="checkbox"/> UPDATE # 2010-083 TO THE ORIGINAL SPILL REPORT		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION Government of Nunavut Airport Land			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES MINUTES SECONDS		LONGITUDE DEGREES MINUTES SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Box 460 Iqaluit. NU. X0A 0H0			
G	ANY CONTRACTOR INVOLVED Nunavut Excavating	CONTRACTOR ADDRESS OR OFFICE LOCATION Box 1984 Iqaluit. NU. X0A 0H0			
H	PRODUCT SPILLED Sewage	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES unknown	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Sewer Main	SPILL CAUSE Clogged Sewer Main	AREA OF CONTAMINATION IN SQUARE METRES 600		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS Two Sewage trucks from the city were called in immediately to pump out AV 262. The spill was contained to an area on the Government of Nunavut Airport Land and Nunavut Excavating was called in to clean up contaminated area. Nunavut Excavating brought in an Excavator and several dump trucks to spill site and removed 113 loads of contaminated snow and ice which was hauled to the Sewage lagoon. The City used their Blaster to remove the blockage which was located between AV-261 and AV-262, the line was blasted and cleared. An open ended sewage pipe on the Airport property was why the sewage pooled in this area. This pipe was capped off to prevent any further reoccurrences. Clean-up was at all times contained to this area, and completed on March 23, 2010 by Nunavut Excavating under the supervision of the City of Iqaluit.				
L	REPORTED TO SPILL LINE BY Rob Hoan	POSITION Utilidor Foreman	EMPLOYER City of Iqaluit	LOCATION CALLING FROM Iqaluit	TELEPHONE 867-222-2941
M	ANY ALTERNATE CONTACT Frank Ford	POSITION PW Superintendent	EMPLOYER City of Iqaluit	ALTERNATE CONTACT LOCATION Iqaluit	ALTERNATE TELEPHONE 867-979-5653
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					