



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 11-02-2011	REPORT TIME 15:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR		REPORT NUMBER
B	OCCURRENCE DATE: MONTH – DAY – YEAR 11-02-2011	OCCURRENCE TIME 08:00	<input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION Access Vault 400, City of Iqaluit			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES MINUTES SECONDS		LONGITUDE DEGREES MINUTES SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Iqaluit. NU. X0A 0H0			
G	ANY CONTRACTOR INVOLVED City of Iqaluit equipment	CONTRACTOR ADDRESS OR OFFICE LOCATION same			
H	PRODUCT SPILLED Sewage	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 5000 litres	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE) none	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Northwestel Sewage service	SPILL CAUSE Partially blocked sewage main	AREA OF CONTAMINATION IN SQUARE METRES 100 m2		
J	FACTORS AFFECTING SPILL OR RECOVERY ice on around	DESCRIBE ANY ASSISTANCE REQUIRED none	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT none		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS On November 02, 2011 at approximately 08:00 it was noticed that a stream of sewage coming out from under the Northwestel building in the City of Iqaluit. 2 sewage trucks, a loader and the sewage blaster were immediately dispatched to the scene, belonging to the City. The flow was immediately contained to the ditch beside Access vault 400, where the sewage trucks were able to vacuum up the sewage which was contained to the ditch, while the sewage blaster removed the partial clog in the sewage main. The sewage main between Access vault 400 and Manhole 07 was partially blocked with grease, causing the excess sewage to travel up Northwestel's sewage service and out onto the ground. After the main was repaired, sewage flow in the main was back to normal. The affected spill area was scraped with the City owned loader, and the contaminated ice and sand was hauled to the lagoon for disposal. with the ground being frozen, the spill only penetrated into the sand approximately one inch, leaving approximately 3 cubic meters of material for disposal. Clean sand was placed in the driveway and ditch to replace what was removed.				
L	REPORTED TO SPILL LINE BY Frank Ford	POSITION PW. Superintendent	EMPLOYER City of Iqaluit	LOCATION CALLING FROM 1554D	TELEPHONE 867-979-5653
M	ANY ALTERNATE CONTACT Shaun Holmes	POSITION Utilidor Forman	EMPLOYER City of Iqaluit	ALTERNATE CONTACT LOCATION 1554D	ALTERNATE TELEPHONE 867-222-2941
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					