

Jan 09 2012 1:30PM City of Iqaluit

8679795910

p.1

12-003



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 979-5524

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH - DAY - YEAR 01-09-12	REPORT TIME 10:30 am	ORIGINAL SPILL REPORT OR UPDATE # TO THE ORIGINAL SPILL REPORT		REPORT NUMBER 12-003
B	OCCURRENCE DATE: MONTH - DAY - YEAR 01-08-12	OCCURRENCE TIME 2:15 pm			
C	LANDUSE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION house #2588		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> Nunavut <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES MINUTES SECONDS		LONGITUDE DEGREES MINUTES SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Iqaluit NU. X0A-0H0			
G	ANY CONTRACTOR INVOLVED narwhal plumbing	CONTRACTOR ADDRESS OR OFFICE LOCATION building 1392			
H	PRODUCT SPILLED Heating Fuel	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 1-2 Litres	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Heating Fuel Tank	SPILL CAUSE Sewage truck backed into tank	AREA OF CONTAMINATION IN SQUARE METRES 4'x5'		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS At approximately 2:15pm on Jan.08 2012 it was reported that a sewage truck backed into a home heating fuel tank at house #2488 in the City of Iqaluit. By-law were called to the scene, where it was noted that approx 1-2 liters of diesel fuel had leaked out of the tank. City of Iqaluit equipment including a loader and several employees with shovels was called to remove the contaminated snow and hauled to Nunatta Environmental disposal yard. Narwhal plumbing have repaired the leak.				
L	REPORTED TO SPILL LINE BY Paul Barrieau	POSITION P.W. Roadforeman	EMPLOYER City of Iqaluit	LOCATION CALLING FROM Iqaluit	TELEPHONE 867-979-5638
M	ANY ALTERNATE CONTACT Kelth Banies	POSITION W.S. Foreman	EMPLOYER City of Iqaluit	ALTERNATE CONTACT Iqaluit	ALTERNATE TELEPHONE 867-979-5512
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> ESD <input type="checkbox"/> CCG <input type="checkbox"/> GANT <input checked="" type="checkbox"/> ION <input type="checkbox"/> RA <input type="checkbox"/> NAC <input type="checkbox"/> NEB <input type="checkbox"/> OTC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY	Robert Earl		01/09/12 11:22		
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR March 24 2012		REPORT TIME 10:00		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR		REPORT NUMBER -
B	OCCURRENCE DATE: MONTH – DAY – YEAR March 23 2012		OCCURRENCE TIME 21:00		<input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER (IF APPLICABLE)			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION AV 341, 2700 block City of Iqaluit					REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES MINUTES SECONDS			LONGITUDE DEGREES MINUTES SECONDS			
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Iqaluit. NU. X0A 0H0				
G	ANY CONTRACTOR INVOLVED City of Iqaluit equipment		CONTRACTOR ADDRESS OR OFFICE LOCATION				
H	PRODUCT SPILLED Sewage		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 3000 litres			U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE) none		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES			U.N. NUMBER	
I	SPILL SOURCE AV 341		SPILL CAUSE Partially blocked Sewage Main			AREA OF CONTAMINATION IN SQUARE METRES 12 M2	
J	FACTORS AFFECTING SPILL OR RECOVERY Snow and Ice		DESCRIBE ANY ASSISTANCE REQUIRED none			HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT none	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS On March 23, 2012 at approximately 21:00 a call was received that there was sewage trickling out of the top of Access Vault 341 in the 2700 block at the City of Iqaluit. Acting Utilidor Foreman Pat Wolfe responded to the scene where he called in 2 sewage trucks to pump out the AV. A sewage blaster was brought in, and the sewage line between AV 341 and AV 340 was immediately blasted and opened. The line appeared to partially blocked with grease and rags. Once sewage flow was re-established to the sewage main, 2 loaders and a backhoe belonging to the City of Iqaluit were brought in to clean up the effected area. Approximately 20 cubic meters of contaminated snow and ice were removed from the site, and disposed of at the City's sewage lagoon. The area was easily cleaned up because the sewage instantly was frozen when exposed to the -30 temperatures. A Public Service Announcement will be prepared explaining to the public the consequences of dumping grease down their drains.						
L	REPORTED TO SPILL LINE BY Frank Ford		POSITION PW Superintendent		EMPLOYER City of Iqaluit		LOCATION CALLING FROM Building 1554D Iqaluit
M	ANY ALTERNATE CONTACT Pat Wolfe		POSITION Act Utilidor Foreman		EMPLOYER City of Iqaluit		ALTERNATE CONTACT LOCATION Building 1554D Iqaluit
TELEPHONE 867-222-2965							
ALTERNATE TELEPHONE 867-222-3433							
REPORT LINE USE ONLY							
N	RECEIVED AT SPILL LINE BY		POSITION Station operator		EMPLOYER		LOCATION CALLED Yellowknife, NT
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC		SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN			FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED		
AGENCY		CONTACT NAME		CONTACT TIME		REMARKS	
LEAD AGENCY							
FIRST SUPPORT AGENCY							
SECOND SUPPORT AGENCY							
THIRD SUPPORT AGENCY							



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR March 24 2012		REPORT TIME 11:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT	REPORT NUMBER -
	B OCCURRENCE DATE: MONTH – DAY – YEAR March 24, 2012		OCCURRENCE TIME 08:30		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES MINUTES SECONDS		LONGITUDE DEGREES MINUTES SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Iqaluit. NU. X0A 0H0		
G	ANY CONTRACTOR INVOLVED City of Iqaluit equipment		CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED Sewage		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES Approx 1000 litre	U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE) none		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE AV 402 City of Iqaluit		SPILL CAUSE Rags blocking sewage main	AREA OF CONTAMINATION IN SQUARE METRES 4 M2	
J	FACTORS AFFECTING SPILL OR RECOVERY -30 temps. snow and ice		DESCRIBE ANY ASSISTANCE REQUIRED none	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT none	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS At approximately 08:30 on March 24 2012, it was noticed by Utilidor Foreman, Pat Wolfe that there was a small amount of sewage leaking from the top of Access Vault 402 across from North Mart in the City of Iqaluit. He immediately called in 2 sewage trucks to pump out the AV. While pumping the vault it was noticed that there were several rags which had blocked the flow inside this vault. Once the rags were removed normal flow was established. There was a small area contaminated with sewage around the effected AV, which was immediately cleaned up with a loader and backhoe supplied by the City of Iqaluit. The contaminated snow and ice that was scraped up at the site consisting of approximately 9 cubic meters which was disposed of at the City's sewage lagoon. The spill was contained by the hard-packed snow, allowing ease of cleanup.				
L	REPORTED TO SPILL LINE BY Frank Ford	POSITION PW Superintendent	EMPLOYER City of Iqaluit	LOCATION CALLING FROM Building 1554D Iqaluit	TELEPHONE 867-222-2965
M	ANY ALTERNATE CONTACT Pat Wolfe	POSITION Utilidor Foreman	EMPLOYER City of Iqaluit	ALTERNATE CONTACT LOCATION 1554D Iqaluit	ALTERNATE TELEPHONE 867-222-3433
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR March 26, 2012		REPORT TIME 10:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT	REPORT NUMBER -
	OCCURRENCE DATE: MONTH – DAY – YEAR March 25, 2012		OCCURRENCE TIME 13:00		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES MINUTES SECONDS		LONGITUDE DEGREES MINUTES SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Iqaluit, NU. X0A 0H0		
G	ANY CONTRACTOR INVOLVED City of Iqaluit equipment		CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED Sewage		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 2000 litres	U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE) none		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES none	U.N. NUMBER	
I	SPILL SOURCE Access Vault 402 Iqaluit		SPILL CAUSE Partially blocked sewage main	AREA OF CONTAMINATION IN SQUARE METRES 10 m2	
J	FACTORS AFFECTING SPILL OR RECOVERY -45 temps. snow and ice		DESCRIBE ANY ASSISTANCE REQUIRED none	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT none	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS At approximately 13:00 on March 25, it was reported that sewage was starting to pool around AV 402 near North Mart. Frank Ford and Pat Wolfe were on site, and immediately called for 2 sewage trucks to pump out the access vault. The spill was contained to the immediate area due to the fridged temperatures, the sewage immediately froze on top of the snow and ice around the AV. Once the AV was pumped out completely, a City owned sewage blaster was able blast the line between AV 402 and 403. A blockage of some sort was observed approximately 100 feet from AV 402, they were able to blast through the blockage and realize normal flow. This area has been set up to be blasted weekly now. A loader and backhoe belonging to the City were called in to cleanup effected area, of which approximately 12 cubic meters of contaminated snow and ice were removed, and disposed of at the City's sewage lagoon. The AV was checked again early Monday morning, and normal unobstructed flow was observed.				
L	REPORTED TO SPILL LINE BY Frank Ford	POSITION PW Superintendent	EMPLOYER City of Iqaluit	LOCATION CALLING FROM Building 1554D Iqaluit	TELEPHONE 867-222-2965
M	ANY ALTERNATE CONTACT Pat Wolfe	POSITION Utilidor Foreman	EMPLOYER City of Iqaluit	ALTERNATE CONTACT LOCATION 1554D Iqaluit	ALTERNATE TELEPHONE 867-222-3433
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR April 04, 2012		REPORT TIME 10:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT	REPORT NUMBER -
	OCCURRENCE DATE: MONTH – DAY – YEAR April 03, 2012		OCCURRENCE TIME 13:30		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES MINUTES SECONDS		LONGITUDE DEGREES MINUTES SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Iqaluit, NU. X0A 0H0		
G	ANY CONTRACTOR INVOLVED City of Iqaluit equipment		CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED Sewage		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 5000 litres	U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE) none		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES none	U.N. NUMBER	
I	SPILL SOURCE Access Vault 402 near Northmart		SPILL CAUSE partially blocked sewage main	AREA OF CONTAMINATION IN SQUARE METRES 15 m2	
J	FACTORS AFFECTING SPILL OR RECOVERY Ice and snow		DESCRIBE ANY ASSISTANCE REQUIRED none	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT none	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS On April 03, at approximately 13:30 it was reported to Utilidor that sewage was flowing out of the top Access vault 402 near Northmart in the City of Iqaluit. Two sewage trucks were immediately called to the scene where the Access vault was pumped out. City of Iqaluit Roads crew was also called in to clean up effected area, and the Utilidor crew blasted the sewage main between Access vault 403 and 402. The blockage was caused by rags, that blocked a restriction in the sewage line, which we suspect to be a partial collapse of the sewage main between AV 402 and 403. The Roads Department scraped up the contaminated area, of which they hauled approximately 50 cubic meters of contaminated snow and ice to the sewage lagoon. This area between AV 402 and 403 will be blasted daily, to keep the restricted area clear until major repairs can be done.				
L	REPORTED TO SPILL LINE BY Frank Ford	POSITION PW Superintendent	EMPLOYER City of Iqaluit	LOCATION CALLING FROM Building 1554D Iqaluit	TELEPHONE 867-222-2965
M	ANY ALTERNATE CONTACT Pat Wolfe	POSITION Utilidor Foreman	EMPLOYER City of Iqaluit	ALTERNATE CONTACT LOCATION 1554D Iqaluit	ALTERNATE TELEPHONE 867-222-3433
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GSWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR April 26, 2012		REPORT TIME 1:15 p.m.	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT	REPORT NUMBER -
	B OCCURRENCE DATE: MONTH – DAY – YEAR April 25 and April 26, 2012		OCCURRENCE TIME 8 p.m. and 7 a.m.		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION Iqaluit			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES MINUTES SECONDS		LONGITUDE DEGREES MINUTES SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION P.O. Box 460 Iqaluit, NU X0A 0H0		
G	ANY CONTRACTOR INVOLVED NA		CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED Sewage		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES Approximately 5000 litres	U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE) NA		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE Access Vault 333		SPILL CAUSE Blockage in the line	AREA OF CONTAMINATION IN SQUARE METRES Approximately 20 sq. meters	
J	FACTORS AFFECTING SPILL OR RECOVERY None		DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS At approximately 8 p.m. on the evening of April 26, 2012, the City was made aware of a sewage overflow at AV 333. A sewage truck was dispatched and began pumping out the AV. The overflow was contained in the immediate area by surrounding snow (there was heavy snowfall throughout the day). The next morning at 7 a.m., the AV overflowed again and another sewage truck was dispatched to pump out the AV. With more resources available in the morning, City staff suspected a blockage of the line and began blasting the line which was soon after completed. The sewage overflow that was contained by the surrounding snow will be removed by City road crews and will be taken to the lagoon at the Waste Water Treatment Plant.				
L	REPORTED TO SPILL LINE BY Arif Savani	POSITION A/Director Utilidor	EMPLOYER City of Iqaluit	LOCATION CALLING FROM Iqaluit	TELEPHONE 867-222-4436
M	ANY ALTERNATE CONTACT	POSITION	EMPLOYER	ALTERNATE CONTACT LOCATION I	ALTERNATE TELEPHONE
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR June 8, 2012		REPORT TIME 8:30 AM	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT	REPORT NUMBER
	B OCCURRENCE DATE: MONTH – DAY – YEAR June 5, 2012		OCCURRENCE TIME 11:00 AM		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION Lift Station #2 Overflow, Iqaluit, Nunavut			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES MINUTES SECONDS		LONGITUDE DEGREES MINUTES SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME City of Iqaluit		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO Box 460 Iqaluit, NU, X0A 0H0		
G	ANY CONTRACTOR INVOLVED NO		CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED Sewage		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 1000 Liters	U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE) NA		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE Sewage line between Lift Station #2 and MH 23		SPILL CAUSE Partially Blocked sewage main	AREA OF CONTAMINATION IN SQUARE METRES 15 square meters	
J	FACTORS AFFECTING SPILL OR RECOVERY Ice		DESCRIBE ANY ASSISTANCE REQUIRED None	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT None	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS At 11:00AM, it was noticed that sewage was coming out of the Lift Station #2 overflow heading into the bay during low tide. Two sewage trucks were immediately dispatched to the scene to pump down the level of sewage in Manhole 23. The Utilidor staff used a blaster and cleared the partial block in the sewage main. Since the spill occurred during low tide, a City backhoe was able to scrape up the sewage and load it into a tandem dump truck. The contaminated ice and sand was hauled to the sewage lagoon for disposal.				
L	REPORTED TO SPILL LINE BY Pat Wolfe	POSITION A/ Utilidor Foreman	EMPLOYER City of Iqaluit	LOCATION CALLING FROM Iqaluit, Nunavut	TELEPHONE 867-222-3433
M	ANY ALTERNATE CONTACT	POSITION	EMPLOYER	ALTERNATE CONTACT LOCATION	ALTERNATE TELEPHONE
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					