



Canada

# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

## REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR <b>02-18th-2013</b>		REPORT TIME <b>10:00am</b>	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT	REPORT NUMBER  -
	OCCURRENCE DATE: MONTH – DAY – YEAR <b>02-17th-2013</b>		OCCURRENCE TIME <b>2:00pm</b>		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION <b>AV25A, next to building 158</b>			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES      MINUTES      SECONDS		LONGITUDE DEGREES      MINUTES      SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME <b>City of Iqaluit</b>		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION <b>City of Iqaluit. PO Box 460. Iqaluit. NU. X0A0H0</b>		
G	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED <b>Sewage</b>		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>2000 liters estimated</b>	U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE <b>Av25A overfilled</b>		SPILL CAUSE <b>Plugged with arease/oil</b>	AREA OF CONTAMINATION IN SQUARE METRES	
J	FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED <b>Sewage truck. road crew</b>	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS  <b>The utilidor personnel on call responded at 2:00pm with an extra crew member with the sewere blaster, also at the same time, called for sewer truck crew to pump out excess sewer from the AV25A, also the road crew called to clear the area for containment. The building 158 next to the AV25A is a local country food store. Where we suspect the collection of country food oil/grease was accumulating in the sanitary next to AV25A.</b>  <b>If you have any questions, you can reach me at 8679793206.</b>				
L	REPORTED TO SPILL LINE BY <b>Paul Keenainak</b>	POSITION <b>Foreman</b>	EMPLOYER <b>City of Iqaluit</b>	LOCATION CALLING FROM <b>Utilidor office</b>	TELEPHONE <b>8679793206</b>
M	ANY ALTERNATE CONTACT	POSITION	EMPLOYER	ALTERNATE CONTACT LOCATION	ALTERNATE TELEPHONE
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION <b>Station operator</b>	EMPLOYER	LOCATION CALLED <b>Yellowknife, NT</b>	REPORT LINE NUMBER <b>(867) 920-8130</b>
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					

