

В

C

D

E

G

Н

03-15-13

03-13-13

LATITUDE

DEGREES

N/A

Sewage

SPILL SOURCE

AV over filled

City of Igaluit

PRODUCT SPILLED



REPORT DATE: MONTH - DAY - YEAR

AV301, Niaqunngusiaq Road

OCCURRENCE DATE: MONTH - DAY - YEAR

LAND USE PERMIT NUMBER (IF APPLICABLE)

MINUTES

SECOND PRODUCT SPILLED (IF APPLICABLE)

FACTORS AFFECTING SPILL OR RECOVERY

RESPONSIBLE PARTY OR VESSEL NAME

ANY CONTRACTOR INVOLVED

REPORTED TO SPILL LINE BY

Paul Keenainak

A ANN ALTERNATE CONTACT

GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION

SECONDS

Canada NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

OCCURRENCE TIME

LONGITUDE

RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION

QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES

QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES

CONTRACTOR ADDRESS OR OFFICE LOCATION

DEGREES

City of Igaluit P.O. Box 460

2000 litres. Approximate.

Rags blocking sanitary

SPILL CAUSE

LOCATION CALLING FROM

lgaluit

WATER LICENCE NUMBER (IF APPLICABLE)

REPORT TIME

1:20pm

12:00pm

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

LI UIII		FAX: (867) 873-6924					
ARDOUS MATERIALS		EMAIL: spills@gov.nt.ca					
		REPORT LINE USE ONLY					
☑ ORIGINAL SPILL REPO	ORT, OR	REPORT NUMBER					
UPDATE# TO THE ORIGINAL SPILL I	REPORT						
JMBER (IF APPLICABLE)							
REGION ☐ NWT ☑ NUNAVUT ☐ ADJACENT JURISDICTION OR							
MINUTES SECO	ONDS						
R OFFICE LOCATION							
DE LOCATION							
OR CUBIC METRES	U.N. NUMI	BER					
OR CUBIC METRES	U.N. NUMI	IBER					

AREA OF CONTAMINATION IN SQUARE METRES

HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT

TELEPHONE

ALTERNATE CONTACT LOCATION ALTERNATE TELEPHONE

867 979 3206

ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAININATED MATERIALS On or about 12:00pm, 13-03-13, the utilidor department responded to a call for AV301 on a seware spill. The department responded

DESCRIBE ANY ASSISTANCE REQUIRED

accordingly, by blasting from AV300. The department blasted repeatedly from AV300 to AV301, along with the seware truck department in pumping out excess sewage from AV301.

The utilidor department noticed rags in the sewer main being blasted through from the direction of AV301.

POSITION

DOCITION

utility systems

K

Keith Couture	ITACT	POSITION Director, public works	City of Iqaluit	ALTERNATE CONTACT LOCATION lqaluit		867 979 5653
RT LINE USE ONLY						
		POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT		REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY EC CCG GNWT GN ILA INAC NEB TC		SIGNIFICANCE MINOR MAJOR UNKNOWN		FILE STATUS ☐ OPEN ☐ CLOSED		
Y	CONTACT NAME		CONTACT TIME	REMARKS		
GENCY						
SUPPORT AGENCY						
ID SUPPORT AGENCY						
SUPPORT AGENCY						
	RECEIVED AT SPILL L	RECEIVED AT SPILL LINE BY RECEIVED AT SPILL LIN	RECEIVED AT SPILL LINE BY RECEIVED AT SPILL LINE BY POSITION Station operator RECEIVED AT SPILL LINE BY POSITION Station operator RECEIVED AT SPILL LINE BY POSITION Station operator RECEIVED AT SPILL LINE BY POSITION STATE RECEIVED	RECEIVED AT SPILL LINE BY POSITION Station operator SIGNIFICANCE MINOR	Received at spill line by Position Station operator Significance Minor Major Unknown Magency Contact name Contact time Remarks Remarks Contact time Remarks Contact name Contact name	Received at spill line by Position Station operator Significance Minor Major Unknown File Station operator Significance Minor Major Unknown Major Unknown Support agency Support agency Support agency Major Maj

EMPLOYER

EMPLOVED

City of Igaluit