



Canada

# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

## REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR <b>06-24-13</b>		REPORT TIME <b>1:00pm</b>	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT	REPORT NUMBER  -
	OCCURRENCE DATE: MONTH – DAY – YEAR <b>06-23-13</b>		OCCURRENCE TIME <b>12:50pm</b>		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE)		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION <b>Lift Station 1</b>			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES      MINUTES      SECONDS		LONGITUDE DEGREES      MINUTES      SECONDS		
F	RESPONSIBLE PARTY OR VESSEL NAME <b>City of Iqaluit</b>		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION <b>P.O. Box 460 Iqaluit. NU X0A 0H0</b>		
G	ANY CONTRACTOR INVOLVED <b>N/A</b>		CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED <b>Raw sewage</b>		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>unknown</b>	U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE) <b>N/A</b>		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE <b>Manhole 1</b>		SPILL CAUSE <b>Power Outage</b>	AREA OF CONTAMINATION IN SQUARE METRES	
J	FACTORS AFFECTING SPILL OR RECOVERY <b>Pump 1 an pump 2 failed</b>		DESCRIBE ANY ASSISTANCE REQUIRED <b>Sewer Truck crew</b>	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS  <b>At about 12:50pm got called for a manhole leaking. Responded by calling all sewer trucks to the site to pump out manhole 1 and from the lift station 1, while the utilidor crew repair pump 1 an 2. Prolonged by failure of the power outage causing failure of the PLC controls. Called an electrician(KRT Electrical) to the site, to troubleshoot the controls. Rags an hard objects found in the pumps. Sewer blasted the suction side of the pump to remove rags in line. The sewer truck crew was at the site pumping from manhole 1 and lift station 1 until the pumps were back in operation. The manhole and the station are next to each other, and are located along the shoreline of Iqaluit.</b>				
L	REPORTED TO SPILL LINE BY <b>Paul Keenainak</b>	POSITION <b>utilidor foreman</b>	EMPLOYER <b>City of Iqaluit</b>	LOCATION CALLING FROM <b>Utilidor shop</b>	TELEPHONE <b>8679793206</b>
M	ANY ALTERNATE CONTACT <b>Keith Couture</b>	POSITION <b>PW Director</b>	EMPLOYER <b>City of Iqaluit</b>	ALTERNATE CONTACT LOCATION <b>Utilidor shop</b>	ALTERNATE TELEPHONE <b>8679795653</b>
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION <b>Station operator</b>	EMPLOYER	LOCATION CALLED <b>Yellowknife, NT</b>	REPORT LINE NUMBER <b>(867) 920-8130</b>
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					

