



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee		Licensee Representative	
Benoit Beauchamp Arctic Institute of North America, University of Calgary 2500 University Drive NW Calgary, AB T2N 1N4 E-mail : bbeaucha@ucalgary.ca		None Present	
Licence No. / Expiry		Representative's Title	
3BC-ACS1313 EXP. 31/12/13			
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
04/07/2014		A.Keim	
Activities Inspected			
<input checked="" type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: Water Discharge <input checked="" type="checkbox"/> Other:			

Conditions:		A - Acceptable		C - Concern		U - Unacceptable		NA – Not Applicable		NI – Not Inspected	
Water Use		Condition	Comment	Site Conditions		Condition	Comment	Haz/Mat Management		Condition	Comment
Intake/Screen	NI			Water Management Structures	NA			Storage	NA		
Flow Measure. Device	NI			Culverts / Bridges	NA			Spills	NA		
Source:				Drainage	NA			Spill Plan	NA		
Water Use:	NI			Erosion / Sediment	NA						
Recirculation (y /n)	N			Mitigation Measures	NA			Administrative			
				Reclamation Activities	NA			Records	NI		
				Materials Storage	NA			Reports	U		2
Waste Disposal				Signage	NA			Plans	A		
Waste Water	NA							Notifications			
Solid Waste	NA			Monitoring			Other				
Hazardous Waste	NA			Sample Collection / Analysis	NA			Comments			1
*The number in the comments field will correspond with specific comments provided below.											
Samples taken by Inspector:				Location(s):							
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No											

SECTION 1	<input checked="" type="checkbox"/> Comments (s.____)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.____)	<input type="checkbox"/> Action Required (s.____)
<p>On July 4th the Inspector attended the site listed in the 2013 Application to inspect the short term/ low impact camp and tenting sites associated with the 3BC-ACS1313 Project. Upon arrival at the general location the inspector noted that no evidence of occupation or disturbance could be seen. No evidence of persons, structures or activities could be seen in the area listed in the application as a camp site. The Camp site location was found in what appeared to be a natural state with no evidence of disturbance. Fuel barrels were found on the adjacent unnamed strip located within the project area and listed with PCSP as the strip that serviced this project.</p> <p>On July 4th the Inspector attended the area around the camp site coordinates listed in the application submitted to the Nunavut Water Board. A review of the Nunavut Water Board web site (FTP site) cannot locate an Annual Report for the above noted file. As such the Inspector cannot confirm the location listed in the application as the sites actually visited by the proponent or whether or not any type of camp or cooking facilities were erected at this or any other location.</p>			
SECTION 2	<input type="checkbox"/> Comments (s.____)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.B (2)_)	<input type="checkbox"/> Action Required (s.____)
<p>On July 4th an inspection of the sites listed in the application was conducted and no evidence of use was found. At this point a recommendation to the Nunavut Water Board to proceed to closure of the License upon a request from the Licensee would be filed with the Record of Inspection. However, the licensee failed in 2011, 2012 and 2013 to file the required Annual Reports with respect to their activities, locations, water use and waste disposal as required by the License.</p> <p>In 2013, following the submission of an application for renewal of this license by the licensee a review of the file showed that the Licensee had not filed the required annual reports in 2011 and at that time, AANDC recommended a renewal not be issued until such time as these reports were submitted. However one was approved by the Board.</p> <p>The Licensee is found to be in contravention of the following section of the renewal License:</p> <p>Part B: General Conditions , Item 2, Annual Reports.</p> <p>Failure to file an Annual Report on the Appurtenant Undertaking with the Board within sixty (60) days of completion of</p>			

the field program, containing the following information:

a. A summary report of water use and waste disposal activities;

b. A list of unauthorized discharges and a summary of follow-up actions taken;

c. A description of all progressive and or final reclamation work undertaken, including photographic records of site conditions before, during and after completion of operations;

d. A summary of all information requested and results of the Monitoring Program; and

e. Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

SECTION 3

☐ Comments (s.____)

☐ Non-Compliance with Act or Licence, (s.____)

☒ Action Required (s.____)

The Licensee has 30 days from receipt of this report to file the required Annual Reports (2011, 2012 and 2013). If annual report(s) have been previously submitted to the NWB, the Proponent is reminded that it is the responsibility of the Licensee to ensure that all submissions to the Board are acknowledged by the licensing department and to ensure it is posted on the Nunavut Water Boards Public Registry.

Failure to do so may result in further enforcement action pursuant to the Nunavut Waters and Nunavut Surface Rights Tribunal Act.

Photo Log

Date	Authorization	Camera	Inspector
July 4, 2014	3BC-ACS1313	Sony Cyber shot	A. Keim




Figure 1 Location of sites listed in License



Figure 2 Camp Location




Figure 3. Unnamed runway with Fuel cache at project coordinates

Licensee or Representative	Inspector's Name
	A. Keim
Signature	Signature
	-Sent by Email- Original on file
Date	Date
	July 5, 2014

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---