NWB Annual Report			Year being reported: 2014 ▼					
License No:	3BC-ALT1015		Issued Date: August 4, 2010 Expiry Date: July 31, 2015					
		_	Expiry Date. Guly 31, 2013					
	Project Name	: :	Canadian Forces Station (CFS) Alert, Nunavut					
	Licensee:	Depart	tment of National Defence - 1 Canadian Air Division					
Mailing Address:			A4 Construction Engineering Department of National Defence - 1 Canadian Air Division PO Box 17000, STN Forces, Winnipeg, MB, R3J 3Y5					
	Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):							
	8 Wing Environmental Management Room 308, Building 22, 74 Polaris Ave. Department of National Defence - 8 Wing/ CFB Trenton Box 1000, Stn Forces Astra, Ontario, K0K 3W0							
General Background Information on the Project (*optional):								
Licence Req	uirements: the		see must provide the following information in accodance					
obtaining wa	ater; sewage a		nd waste disposal activities, including, but not limited to: methods of ywater management; drill waste management; solid and hazardous					
waste mana		(c):	Upper Dumbell Lake, Nunavut.					
	Water Source(Water Quantity		185 Quantity Allowable Domestic (cu.m) 406 Actual Quantity Used Domestic (cu.m) Quantity Allowable Drilling (cu.m) Total Quantity Used Drilling (cu.m)					
	Solid V Sewag Drill W Greyw Hazard Other: Additional Deta Appendix A: M Appendix B: M	Waste Dis ge /aste rater dous ails: lonitorir	Landfarms ng Program Station No. ALT-1 ng Program Stations No. ALT-2-3					
			ng Program Stations No. ALT-4-5-6-7 ng Program Stations No. ALT-8-9-10-11					

Appendix E: June Analysis Results for ALT-4-5-6-8-9-10

Appendix F: July Analysis Results for ALT-4 Appendix G: August Analysis Results for ALT-4 Appendix H: July Analysis Results for ALT-8

Appendix I: List of Waste Disposal Activities / Copies of Movement Documents

Appendix J: Progressive and Final Reclamation Work Undertaken Appendix K: Revised Quality Assurance & Quality Control (QA/QC) Plan

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: 14-448 (as reported to the Spill Hot-line)

Date of Spill: 14-12-2014

Date of Notification to an Inspector: 15-12-2014

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

A break in the heat recovery pipeline released 600L of ethylene glycol outside between the CFS Alert Supply Ware House and Power Plant. Working under extremely cold weather, 3 barrels of glycol contaminated snow was recovered for hazwaste disposal. Corrosion of the copper pipeline was determined to be the cause; this section was replaced. A project file was raised to inspect the entire heat recovery pipeline in summer 2015. No impacts to water bodies.

Revisions to	o the Spill Contingency Plan
	SCP submitted and approved - no revision required or proposed ▼
	Additional Details:
	No reivisions required.
Revisions to	o the Abandonment and Restoration Plan
	AR plan submitted and approved - no revision required or proposed ▼
	Additional Datailar
	Additional Details: No revisions required.
	The revisions required.
Progressive	e Reclamation Work Undertaken
. regiocolii	Additional Details (i.e., work completed and future works proposed)
	See Appendix M.
Results of t	the Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;
	Details described below
	Additional Details:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
	each location where wastes associated with the licence are deposited;
	Details described below
	Additional Details:
	Additional Details:
	Additional Details:
	Additional Details: Results of any additional sampling and/or analysis that was requested by an Inspector
	Results of any additional sampling and/or analysis that was requested by an Inspector Select
	Results of any additional sampling and/or analysis that was requested by an Inspector

_	details on water use or waste disposal requested by the Board by November 1 of the year	
being repo	rted.	
	No additional sampling requested by an Inspector or the Board	
	Additional Details: (Attached or provided below)	
Any respor	nses or follow-up actions on inspection/compliance reports	
	No inspection and/or compliance report issued by INAC ▼	
	Additional Details: (Dates of Report, Follow-up by the Licensee)	
Any addition	onal comments or information for the Board to consider	
	A. At the time of this Annual Report submission, DND is also submitting a Water Licence amendment/renewal application to renew the licence and to address	

B. DND contracted a new laboratory service provider and has revised the Quality Assurance and Quality Control (QA/QC) Plan within the the Operation &

2) Addition of a new Landfarm Facility at ALT-10, DND requests similar SNP

1) Increase Water Usage limit (Intake, Return, Consumption limits);

Maintenance (O&M) Plan for CFS Alert. Only the revised QA/QC Plan is submitted for the NWB approval; the remainder of the O&M Plan did not require revisions and is not attached.

Date Submitted: Submitted/Prepared by:

March 31, 2015

conditions as the current Landfarm at ALT-11.

Andrew Tam, PhD

Contact Information:

613-392-2811 ext 4821 Tel:

Fax: 613-965-3368

compliance issues:

email: Andrew.Tam@forces.gc.ca

GPS Coordinates for water sources utilized

	Latitude			Longitude		
Source Description	o Deg	, Min	, Sec	o Deg	, Min	Sec.
Upper Dumbell Lake	82	29	6.2	-62	28	9.5
			\dashv			
			4			

GPS Locations of areas of waste disposal

Location	Latitude			Longitude		
Description	Deg	, Min	Sec	Deg	Min	Sec
(type)	0	,	"	0	,	"
Alert Battery						
Dump	82	29	16	-62	23	15.32
Alert Main						
Station						
Landfill	82	30	17	-62	20	14.89
Alert Dump #						
3	82	29	18	-62	20	57.01
Landfarm						
(ALT-11)	82	30	40	-62	18	37.6
Millionaire's	82			-62		30.4
Dump		29	19		21	
Sewage	82	29	56	-62	21	4.8
Terrace/Outf						
all						
Landfarm	82	29	58	-62	21	16
(ALT-10,						
new)						