



WATER LICENCE INSPECTION FORM

☑ Original☐ Follow-Up Report

Licensee Licensee Representative								
Dr. Gordon Osinski			None Pr	None Present				
Department of Earth Sciences,								
University of Western Ontario,								
1151 Richmond Street,								
London, ON N6A 5B7								
Email: gosinski@uwo.ca								
mbeauch6@uwo.ca								
Licence No. / Expiry Representative's Title								
3BC-AMD 1212 EXP. 31/12/12								
Land / Other Authorizations Land / Other Authorizations								
Land / Other radionizations								
Date of Inspection			Inspector					
· · · · · · · · · · · · · · · · · · ·								
05/07/2014 A.Keim								
Activities Inspected ⊠ Camp	☐ Drilling	☐ Mining	□ Cor	struction	Reclamation	☐ Fuel Storage		
Roads/Hauling	Other: Water Discl		⊠ Oth					
	cceptable	C - Concern	U - Unaccept	able	NA – Not Applicable	NI – Not Inspected		
Water Use	Condition Commen	Site Conditions	;	Condition	Comment Haz/Mat Manage	ement Condition Comment		
Intake/Screen	NI	Water Managem	ent Structures	NA	Storage	NA		
Flow Measure. Device	NI	Culverts / Brido	Culverts / Bridges		Spills	NA		
Source:		Drainage	Drainage		Spill Plan	NA		
Water Use:	NI	Erosion / Sediment		NA				
Recirculation (y /n)	N	Mitigation Mea	Mitigation Measures		Administrative			
, ,		Reclamation Ac		NA	Records	NI		
		Materials Stora		NA	Reports	A		
Waste Disposal		Signage		NA	Plans	A		
Waste Water	NA	ggo			Notifications			
Solid Waste	NA NA	Monitoring	Monitoring		Other			
			Sample Collection / Analysis		Other			
Hazardous Waste	NA	Sample Collect	on / Analysis	NA				
*7	The number in the	comments field w	ill correspond v	vith speci	ific comments provided belo)W.		
Samples taken by Inspe	ector:	Location(s):						
☐ Yes ⊠ No								
CECTION 4	7 0	\ Nam	Oli	41a A a 4 a a	- Li /- \	tion Dominad (a)		
_	Comments (s		Compliance wi			tion Required (s)		
			ual report from	1 2012 to	inspect the short term/ lov	v impact camp and		
tenting sites associated	I with the 3BC-AN	ID1212 Project.						
Upon arrival at both sites the inspector noted that no evidence of occupation or disturbance could be seen. No persons, structures								
or activities could be seen in the area.								
The sites were both found in what appeared to be their natural state with no evidence of disturbance.								
SECTION 2								
Click here to enter text.								
SECTION 3	Comments (s	_) Non-	Compliance wi	th Act or	Licence, (s) Ac	tion Required (s)		
Click here to enter	text.							







Figure 1. Location of camp coordinates



Figure 2 Camp coordinates, large salt mound



Figure 3 view away from camp





Affaires autochtones et Développement du Nord Canada

Licensee or Representative	Inspector's Name
	A.Keim
Signature	Signature
	-Sent by Email- Original on file
Date	Date
	July 5, 2014

Office Use Only:	Follow-up report to be issued by Inspector	☐ Yes No

