



WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee		Licensee Representative	
Canadian Wildlife Service			
Licence No. / Expiry		Representative's Title	
3BC-ASP1111			
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
28 July 2018		Baba Pedersen	
Activities Inspected			
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:	<input type="checkbox"/> Other:	<input checked="" type="checkbox"/> Reclamation
		<input checked="" type="checkbox"/> Fuel Storage	

Conditions:		A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected	
Water Use		Condition	Comment	Site Conditions		Condition	Comment
Intake/Screen				Water Management Structures			
Flow Measure. Device				Culverts / Bridges			
Source:				Drainage			
Water Use:				Erosion / Sediment			
Recirculation ( y /n)				Mitigation Measures			
				Reclamation Activities		A	2
				Materials Storage			
Waste Disposal				Signage			
Waste Water							
Solid Waste				Monitoring			
Hazardous Waste				Sample Collection / Analysis			
*The number in the comments field will correspond with specific comments provided below.							
Samples taken by Inspector:		Location(s):					
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		No Samples taken on this Inspection					

SECTION 1	<input checked="" type="checkbox"/> Comments (s.__)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.__)	<input type="checkbox"/> Action Required (s.__)
On July 28, 2018 I Inspected the Canadian Wildlife Service (CWS) Camp Site which was located on Prince of Wales Island.			
SECTION 2	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
1. At the Airfield located at N 72° 59' 23.7" W 98° 58' 48.8" I found a Fuel Cache (Photos 1, 2 & 3) consisting of 5 Full Drums and 2 Empty Drums. 2. At the Camp Site Area (Photos 4, 5 & 6) located at N 72° 59' 27.5" W 98° 58' 48.5" I found the area in a Clean and Natural State.			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required
1. The Fuel Cache is within allowable limits without a Permit. 2. The Camp Site has been Cleaned Up and Removed as required. I RECOMMEND CLOSURE OF WATER LICENSE 3BC-ASP1111.			

Licensee or Representative	Inspector's Name
	Baba Pedersen
Signature	Signature
	Signed Original on File
Date	Date
	28 July 2018

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

cc. CIRNAC, Director of Lands, Iqaluit, [erik.allain@canada.ca](mailto:erik.allain@canada.ca)  
Nunavut Water Board, Manager of Licensing, Gjoa Haven, [licensing@nwb-oen.ca](mailto:licensing@nwb-oen.ca)





PHOTO LOG

Date	Camera	Inspector	Authorization
28 July 2018	Sony DSC-HX50V	Baba Pedersen	3BC-ASP1111
Photo Log # DSC03265		Location N 72°59'23.7" W 98°58'48.8"	

Photo 1



Description: 7 Fuel Drums on Site/5 Full/2 Empty

Photo Log # DSC03268

Location N 72°59'23.7" W 98°58'48.8"

Photo 2



Description: Close up of Drum Label – CWS Rausch 2010 Cambridge Bay





Photo Log # DSC03280

Location N 72°59'23.7" W 98°58'48.8"

Photo 3



Description: GPS showing Location of 7 Drums

Photo Log # DSC03284

Location N 72°59'27.5" W 98°58'48.5"

Photo 4



Description: View #1 of CWS Camp Site Area – All Cleaned Up





Photo Log # DSC03287

Location N 72°59'27.5" W 98°58'48.5"

Photo 5



Description: View #2 of CWS Camp Site Area – All Cleaned Up

Photo Log # DSC03291

Location N 72°59'27.5" W 98°58'48.5"

Photo 6



Description: GPS showing Location of CWS Camp Site Area