



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee		Licensee Representative	
Department of National Defence		Éric Trépanier	
Licence No. / Expiry		Representative's Title	
3BC-AWW0814 – Expired		Director Land Environment Chief of Land Staff	
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
08/08/14		A.Keim	
Activities Inspected			
<input type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage			
<input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: Water Discharge <input checked="" type="checkbox"/> Other: winter camp site			

Conditions:		A - Acceptable		C - Concern		U - Unacceptable		NA – Not Applicable		NI – Not Inspected	
Water Use		Condition	Comment	Site Conditions		Condition	Comment	Haz/Mat Management		Condition	Comment
Intake/Screen	NA			Water Management Structures	NA			Storage	NA		
Flow Measure. Device	NA			Culverts / Bridges	NA			Spills	NA		
Source:	NA			Drainage	NA			Spill Plan	NA		
Water Use:	NA			Erosion / Sediment	NA						
Recirculation (y /n)	NA			Mitigation Measures	NA			Administrative			
				Reclamation Activities	NA			Records	NA		
				Materials Storage	NA			Reports	C		A
Waste Disposal				Signage	NA			Plans	NA		
Waste Water	NA							Notifications	NA		
Solid Waste	NA			Monitoring		Other					
Hazardous Waste	NA			Sample Collection / Analysis	NA						
*The number in the comments field will correspond with specific comments provided below.											
Samples taken by Inspector:				Location(s): 75°05' 00"N 96°28' 00"W, and on the Polaris mine suite property at N75° 23' 14.3" W096° 55' 41.9"							
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No											

SECTION 1	<input checked="" type="checkbox"/> Comments (s.__)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.__)	<input type="checkbox"/> Action Required (s.__)
<p>On July 8th 2014the Inspector attended and over flew a number of the listed sites contained within the application for the issued Water License around Resolute Bay. Upon arrival at the locations listed the inspector noted that no evidence of occupation or disturbance could be seen. No persons, structures or activities could be seen in the area. The sites inspected were found to be in their natural state with no evidence of disturbance.</p> <p>A review of the Nunavut Water Board web site (FTP site) did not at the time of the writing of this report locate Annual Reports for the above noted file. As such the Inspector could confirm the locations as listed in the application as those actually visited by the proponent.</p> <p>Following this the Licensee filed all outstanding reports and these have been reviewed and accepted by the NWB.</p> <p>The Inspector of record for the file, 3BC-AWW0814 , recommends closure of the file to the Nunavut Water Board.</p>			
SECTION 2	<input type="checkbox"/> Comments (s.__)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.__)	<input type="checkbox"/> Action Required (s.__)
Click here to enter text.			
SECTION 3	<input type="checkbox"/> Comments (s.__)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s.__)	<input type="checkbox"/> Action Required (s.__)
Click here to enter text.			

Licensee or Representative	Inspector's Name
	Andrew Keim
Signature	Signature
	Original on file
Date	Date
	14/04/2016

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input type="checkbox"/> No
------------------	--	--