

**NWB Annual Report**

**Year being reported:** 2009 ▼

**License No:** 3BCDIG0812 **Issued Date:** October 6, 2008  
**Expiry Date:** August 31, 2012

**Project Name:** East Digges Island Camp

**Licensee:** Environment Canada (Carleton University)

**Mailing Address:** Carleton University,  
 1125 Colonel By Drive, Raven Road,  
 Ottawa, Ontario  
 K1A 0H3

**Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):**

Environment Canada

**General Background Information on the Project (\*optional):**

Biological field camp.

**Licence Requirements: the licensee must provide the following information in accordance with**

Part B ▼ Item 1 ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):	STREAM		
Water Quantity:	5cu.m/day	Quantity Allowable Domestic (cu.m)	
	0.1cu.m/day	Actual Quantity Used Domestic (cu.m)	
		Quantity Allowable Drilling (cu.m)	
		Total Quantity Used Drilling (cu.m)	

**Waste Management and/or Disposal**

- ☐ Solid Waste Disposal
- ☒ Sewage
- ☐ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

**Additional Details:**

A maximum of 0.01m3 of grey water poured into a sump daily.  
 Sump filled in on the final day at camp.  
 Solid sewage bagged and removed to Iqaluit for disposal at the end of the 8 day occupation of the camp.

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

**Revisions to the Spill Contingency Plan**

SCP addendum attached for Board consideration



Additional Details:

**Revisions to the Abandonment and Restoration Plan**

No Abandonment and Restoration (AR) Plan submitted or approved



Additional Details:

**Progressive Reclamation Work Undertaken**

Additional Details (i.e., work completed and future works proposed)

N/A Work continues

**Results of the Monitoring Program including:**

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Select



Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details described below



Additional Details:

---

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

Camp occupied for 8 person-days in 2009

**Date Submitted:**

October 20, 2010

**Submitted/Prepared by:**

A.J.Gaston (original) - Christine Eberl (2016 amendment)

**Contact Information:**

**Tel:** 613-998-8282

**Fax:** 613-998-0458

**email:** [christine.eberl@canada.ca](mailto:christine.eberl@canada.ca)