NWB Annual	Report	Year being reported: 2013 ▼					
License No:	3BC-EAS1214 Type	"B"					
1	Project Name:	East Bay Biological Field Camp					
1	Licensee: Envir	conment Canada (Carleton University)					
	Mailing Address:	National Wildlife Research Center 1125 Colonel By Drive Ottawa, ON K1A 0H3					
	Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):						
	Environment Canad	da					
General Back	ground Information	n on the Project (*optional):					
Licence Requirements: the licensee must provide the following information in accodance with Part B Item 1 A summary report of water use and waste disposal activities, including, but not limited to: methods of							
	er; sewage and gre	eywater management; drill waste management; solid and hazardous					
	Water Source(s): Water Quantity:	Sea Ice and Snow, Flowing Creek 5 cu.m/day					
,	Waste Management and/or Disposal Solid Waste Disposal						
<u>ئے</u>	✓ Sewage ☐ Drill Waste ✓ Greywater ☐ Hazardous ☐ Other: Additional Details:						

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.:		(as reported to	the Spill Ho	ot-line)		
	Date of Spill: Date of Notific	cation to an Inspecto	r:				
		tails: (impacts to water, r		es, short/long te	erm monitoring,	etc)	-
Revisions to t	he Snill Con	tingency Plan					
	Select	ingency i lan				•	
, ,	Additional Det	rails:					
Ĺ	taditional Bet	uno.					
.							_
	:ne Abandoni Select	ment and Restorati	ion Plan			_	
ı							
<i>,</i>	Additional Det	alls:					7
L							_
		Work Undertaken tails (i.e., work comp	lated and future	o worke proj	nosad)		
, [ieleu anu iuluit	e works proj	poseu)		1
	N/A work co	munues					
L							
Results of the	Monitoring	Program including	:				
		ordinates (in degre			s of latitude	and longitu	de) of
	Details described	d below				•	
A	Additional Det	ails:					
	depending o	ered from sea ice an on the quality of the "N, 81° 41' 43.9W.					
		ordinates (in degre n where wastes ass				_	de) of
	Details described	i below				_	
A	Additional Det	ails:					_
	Mainland ca	amp: 63°59'14.1"N,	81°41'43.9				

Results of any additional sampling and/or analysis that was requested by an Inspector

No a	dditional sampling requested by an Inspector or the Board					
Add	Additional Details: (date of request, analysis of results, data attached, etc)					
Any other details being reported.	on water use or waste disposal requested by the Board by November 1 of the year					
No a	dditional sampling requested by an Inspector or the Board					
Addi	itional Details: (Attached or provided below)					
	r follow-up actions on inspection/compliance reports spection and/or compliance report issued by INAC					
140 11	ispection and/or compliance report issued by INAC					
Addi	itional Details: (Dates of Report, Follow-up by the Licensee)					
Any additional co	amments or information for the Board to consider					
Any additional co	omments or information for the Board to consider					
Date Submitted: Submitted/Prepar Contact Informati						