

WATER LICENCE INSPECTION FORM


☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Geological Survey of Canada	Keith Dewing
Licence No. / Expiry	Representative's Title
3BC-ERI1011	Research Scientist
Land / Other Authorizations	Land / Other Authorizations
N2009N0010	
Date of Inspection	Inspector
July 6, 2019	Joseph Monteith, Jeremy Fraser, and Erik Allain
Activities Inspected	
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input type="checkbox"/> Other:
	<input checked="" type="checkbox"/> Reclamation
	<input checked="" type="checkbox"/> Fuel Storage

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
PART:	Condition		Observation No.*		
A: SCOPE, DEFINITIONS AND ENFORCEMENT	NI				
B: GENERAL CONDITIONS	A				
C: CONDITIONS APPLYING TO SECURITY	NI				
D: CONDITIONS APPLYING TO WATER USE	A		1		
E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT	A		2,3,4		
F: CONDITIONS APPLYING TO MODIFICATIONS	NI				
G: CONDITIONS APPLYING TO CONSTRUCTION	NI				
H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING	NI				
I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING	A				
J: CONDITIONS APPLYING TO MONITORING	A				
SCHEDULES	A				
*The observation number corresponds with specific comments provided below.					
Samples taken by Inspector:	Location(s): N78°13'14, W101° 4' 34" Camp				
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

SECTION 1	<input type="checkbox"/> Comments (s.__)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.__)	<input type="checkbox"/> Action Required (s.__)
BACKGROUND The Geological Survey of Canada was issued 3BC-ERI1011on March 11, 2010 and was authorized to withdrawal 5 cubic metres of water per day. The licence was set to expire on September 30, 2011. The camp occupied an area roughly 150m x 200 m 3Ha and included 7 sleeping tents, a cook tent, and an office tent.			
Inspector Statement On July 7, 2019 at 9:30am, A Water Licence Inspection was conducted by Water Resource Officer Joseph Monteith, Jeremy Fraser, and Erik Allain at Ellef Ringes Island, Qikiqtani Region, Nunavut, for water licence 3BC-ERI1011. The inspection was complete on July 7, 2019 at 11:50am.			
General Condition On February 11, 2015 an email sent to Andrew Keim, from Phyllis Beaulieu, Nunavut Water Board, acknowledging receipt the submission of the 2010, and 2011 annual reports.			
Water Supply Facilities 1. No sign of water withdrawal (photo 1)			
Waste 2. No signs of Grey Water Sump (photo 1) 3. No sign of Latrine Sump(photo 1)			
Fuel Cache 4. No signs of a fuel cache, or spills (photo 1 & 2)			
SECTION 2	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
I recommend closure.			
SECTION 3	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Click here to enter text.			

Licensee or Representative	Inspector's Name
	Joseph Monteith
Signature	Signature
	
Date	Date
	February 13, 2020

CC: Licensing Department, NWB
Justin Hack, Manager of Field Operations, CIRNAC

PHOTO LOG


Date	Camera	Inspector	
July 7, 2019	Nikon Cool Pix	Joseph Monteith	Ellef Ringes Island, NU
Photo Log #	Location		
Photo 1	N79° 13' 14" W101° 4' 34"		
			
Description: Site of camp location. 7 tents, a cook tent, and an office tent were at this site.			

Photo Log #	Location
Photo 2	Ellef Ringes Island, NU
	
Description: to access the site the proponents used Panarctic Hercules Runway to access the site. No equipment, structures, or footprint.	