| NWB Annua | l Report | Year being reported: 2012 ▼ | | | | | | |
|---------------------|--|--|--|--|--|--|--|--|
| License No: | 3BC-FCA1212 | Issued Date: June 11, 2012 Expiry Date: December 31, 2012 | | | | | | |
| | Project Name: | Flora of the Canadian Arctic | | | | | | |
| | Licensee: Dr. Jeffery M. Saarela | | | | | | | |
| | Mailing Address: | P.O. Box 3443, Station D, Ottawa, Ontario, K1Y 1X7, Canada Canadian Museum of Nature | | | | | | |
| | • • | filing Annual Report (if different from Name of Licensee please clarify e two entities, if applicable): | | | | | | |
| General Bac | kground Information | on the Project (*optional): | | | | | | |
| Licence Req with | | see must provide the following information in accodance | | | | | | |
| | ater; sewage and gre | and waste disposal activities, including, but not limited to: methods of eywater management; drill waste management; solid and hazardous | | | | | | |
| | Water Source(s): Water Quantity: | Soper River, Fundo lake 5 | | | | | | |
| | Waste Management Solid Waste Dist Sewage Drill Waste Greywater Hazardous Other: Additional Details: | | | | | | | |

A list of unauthorized discharges and a summary of follow-up actions taken.

| | Spill No.: | | (as | repo | rted to | the S | Spill Ho | ot-line) | | | |
|--------------|--|----------------------|--------|------|---------|-------|----------|----------|--|---|--|
| | Date of Spill: | | | | | | | | | | |
| | Date of Notific | ation to an Inspecto | or: | | | | | | | | |
| | Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc) | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| Revisions to | the Spill Con | tingency Plan | | | | | | | | | |
| | N/A - not applica | | | | | | | | | • | |
| | | | | | | | | | | | |
| | Additional Det | ails: | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| Revisions to | the Abandon | ment and Restorati | tion F | Plan | | | | | | | |
| | N/A - not applica | able | | | | | | | | • | |
| | | | | | | | | | | | |
| | Additional Det | ails: | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

All reclamation work for sites erected was completed during the licence period. Water was taken directly from the Soper River using a jug or handheld water pump, with no impact to the landscape, therefore, no reclamation work was necessary for the water extraction sites.

For the sump sites, shallow holes (10-20 cm), were dug into the soil for the disposal of wastewater. At the end of their use, each sump site was filled in with the original displaced soil leaving no impressions in the tundra. For the pit latrines, each pit was dug to 1 meter deep and 20 cm across. These were incrementally filled with some of the displaced dirt during each use, and each was filled in completely at the end of each use filled completely with displaced soil. All markers were removed from pit sites, leaving the location in its original state.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

| | Details described below |
|---|--|
| 4 | additional Details: |
| | 63°14′55.5″N, 69°36′20.6″W |
| | 63°09′46.9″N, 69°39′25.7″W 63°06′34.4″N, 69°43′40.3″W |

62°59'06.9"N, 69°43'06.0"W 62°50'48.5"N, 69°53'36.1"W The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited; Details described below ▼ Additional Details: 63°14'54"N, 69°36'23"W 63°14'53.99"N.69°36'22.99"W 63°09'46.4"N, 69°39'23.9"W 63°09'44.0"N, 69°39'23.0"W 63°06'46.4"N, 69°43'41.7"W 63°06'30.3"N, 69°43'41.4"W 62°59'02.4"N, 69°43'02.9"W 62°59'02.0"N, 69°43'02.9"W Results of any additional sampling and/or analysis that was requested by an Inspector No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below) Any responses or follow-up actions on inspection/compliance reports No inspection and/or compliance report issued by INAC Additional Details: (Dates of Report, Follow-up by the Licensee) Any additional comments or information for the Board to consider

| Date Submitted: | March ' | 14th, 2014 | | | | |
|------------------------|------------------------|------------------------|--|--|--|--|
| Submitted/Prepared by: | Dr. Jeffery M. Saarela | | | | | |
| Contact Information: | Tel: | 613-386-4080 | | | | |
| | Fax: | 613-364-4027 | | | | |
| | email· | isaarela@mus-nature.ca | | | | |