

## NWB Annual Report

Year being reported:

2014 ▼

License No: 3BC-GBI1114 TYPE "B"

Issued Date: March 11, 2011

Expiry Date: March 31, 2014

Project Name: Belcher Islands Biological Field Camp

Licensee: Environment Canada (Carleton University)

Mailing Address:

National Wildlife Research Center  
1125 Colonel By Drive  
Ottawa, ON  
K1A 0H3

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Environment Canada

## General Background Information on the Project (\*optional):

We operate a small field camp to support our studies of migratory birds.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼

Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Sea Ice and Snow		
Water Quantity:	5 cu.m/day	Quantity Allowable Domestic (cu.m)	
	1 cu.m/day	Actual Quantity Used Domestic (cu.m)	
		Quantity Allowable Drilling (cu.m)	
		Total Quantity Used Drilling (cu.m)	

## Waste Management and/or Disposal

- ☐ Solid Waste Disposal  
☒ Sewage  
☐ Drill Waste  
☒ Greywater  
☐ Hazardous  
☐ Other:

Additional Details:

Greywater was disposed of in a snow sump near the cabin. Holes were dug in the snow for sewage disposal at least 150 m from the pond and cabin and where the high tide line was thought to be (crew were at the camp for 7 days in the winter)

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

#### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

#### Revisions to the Abandonment and Restoration Plan

N/A - not applicable



Additional Details:

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

#### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details described below



Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details described below



Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

**Date Submitted:**

Jul. 03, 2018

**Submitted/Prepared by:**

Holly Hennin

**Contact Information:**

**Tel:** 613 991 9973

**Fax:** 613 998 0458

**email:** [holly.hennin@canada.ca](mailto:holly.hennin@canada.ca)