



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee		Licensee Representative	
Professor Shawn Marshall University of Calgary		Shawn.marshall@ucalgary.ca	
Licence No. / Expiry		Representative's Title	
3BC-GCS1313			
Land / Other Authorizations			
Date of Inspection		Inspector	
02 July 2017		Justin HACK	
Activities Inspected			
<input type="checkbox"/> Municipality	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input checked="" type="checkbox"/> Other: Camp	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage
<input type="checkbox"/> Other:			

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected
Water Use	Condition	Comment	Site Conditions	Condition	Comment
Intake/Screen			Water Management Structures		
Flow Measure. Device			Culverts / Bridges		
Source:			Drainage		
Water Use:			Erosion / Sediment		
Recirculation (y /n)			Mitigation Measures		
			Reclamation Activities	A	
			Materials Storage		
Waste Disposal			Signage		
Waste Water					
Solid Waste			Monitoring		
Hazardous Waste			Sample Collection / Analysis		
*The number in the comments field will correspond with specific comments provided below.					
Samples taken by Inspector:			Location(s): GLACIER- CLIMATE STUDIES, PRINCE OF WALES ICEFEILD PROJECT QIKIQTANI REGION, NUNAVUT		
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Background: Nunavut Water Licence 3BC-GCS1313, issued to Shawn Marshall at the University of Calgary, allowed for the use of 5cubic metres of water and the deposit of waste between the dates of June 24, 2013 and December 31, 2013. This licence was to support research activities at the Glacier-Climate Studies Prince of Wales Icefield Project located at Ellesmere Island at the GPS co-ordinates of N78 02 50 and W82 07 00.			
Inspectors Statement: On July 2, 2017 an inspection was conducted at the general location of the camp facilities to ensure all uses of water and deposits of waste had ceased. No uses of water or deposits of waste in contravention of section 12 of the Nunavut Waters and Nunavut Surface Rights Tribunal Act were noted. Based on the evidence made available to INAC and the site inspection, no concerns were noted with the site and no further inspection of this site related to this project will be conducted.			

Inspector's Name	
Justin Hack	
Signature	
Date	
September 6, 2017	