

WATER LICENCE INSPECTION FORM

Original	
Follow-Up Repor	_

Licensee	_		censee Representative						
Ms. Patricia Sutherl	and		N/A						
Licence No. / Expiry Representative's Title									
3BC-HAP1111 Land / Other Authorizations Land / Other Authorizations									
8WLC-HAP1516									
Date of Inspection Inspector									
July 9, 2018 Jonathan Mesher									
	Drilling Other:	☐ Mining ☐	☐ Mining ☐ Construction ☐ Reclamation ☐ Fuel Storage ☐ Other:						
	Acceptable	C - Concern U - Unacce		NA – Not Applicable	NI – Not Inspe	cted			
Water Use		Site Conditions		Commen Haz/Mat					
	Condition Comr	ment	Condition	t Management	Condition Co	omment			
Intake/Screen	A	Water Management Structures	А	Storage	A				
Flow Measure. Device	A	Culverts / Bridges	А	Spills	А				
Source:	Α	Drainage	А	Spill Plan	A				
Water Use:	Α	Erosion / Sediment	А						
Recirculation (y /n)	N	Mitigation Measures	А	Administrative					
		Reclamation Activities	Α	Records	Α				
		Materials Storage	Α	Reports	U				
Waste Disposal		Signage	А	Plans	А				
Waste Water	A			Notifications	А				
Solid Waste	A	Monitoring		Other					
Hazardous Waste	А	Sample Collection / Analys	is NI						
*7	he number in t	the comments field will correspor	nd with specif	fic comments provided belo	W.				
Samples taken by Insp	ector:								
☐ Yes ⊠ No									
SECTION 1	Comments (s	S) Non-Compliance	with Act or	Licence (s) Act	ion Required (s				
On July 9th, 2018 A Water Licence inspection was conducted by J.Mesher of CIRNAC to ensure compliance with the Water licence 3BC-HAP/8WLC-HAP. While on site there was no evidence water usage or deposits of waste at the location: N62 39 00.0 W69 34 01.2. If the NWB or the licensee has no objections or plans for future uses of water and/or deposits of waste the inspector is satisfied with the closure of this licence.									
_	_								
SECTION 2	Comments	Non-Compliance	with Act or	Licence Act	ion Required				
Click here to enter text									
SECTION 3	Comments	Non-Compliance	e with Act or	Licence Act	ion Required				
Click here to enter text									
Lineane en Demanantative		I Inc.	mantania Nama						
Licensee or Representative Ms. Patricia Sutherl	land		Inspector's Name Jonathan Mesher						
Signature	id id		ignature						
•									
Date		-	Date						
Dale		·	Date August 10, 2018						
Office Use Only: Follow-up report to be issued by Inspector									

CC: Licensing Department, NWB

Justin Hack, Manager of Field Operations, CIRNAC

