

NWB Annual Report

Year being reported: 2011



License No: 3BC-HAP1111

Issued Date: 2011

Expiry Date: 2012

Project Name: Helluland Archaeology Project

Licensee: Patricia D. Sutherland

Mailing Address:
Canadian Museum of Civilization
1 rue Laurier, Gatineau QC, K1A 0M8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Patricia D. Sutherland, Northlands Research, 1154 Bayview Drive, Woodlawn ON, K0A 3M0

General Background Information on the Project (*optional):

Small archaeological tent camp (7 people) occupied July 5 to August 9 2011.

Licence Requirements: the licensee must provide the following information in accordance with

Select



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	local pond	
Water Quantity:	1	Quantity Allowable Domestic (cu.m)
	1	Actual Quantity Used Domestic (cu.m)
	0	Quantity Allowable Drilling (cu.m)
	0	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☒ Sewage
- ☐ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

Sewage buried
Greywater spread on vegetated surface

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No spills

Revisions to the Spill Contingency Plan

N/A - not applicable



Additional Details:

Revisions to the Abandonment and Restoration Plan

NA- not applicable



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Select



Additional Details:

Water obtained by bucket from pond located at 62°39'21"N, 69°33'47"W

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below



Additional Details:

Greywater disposal and sewage burial at
 62°39'20.25"N, 69°34'17.23"W

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC



Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

The site was visited in 2013 by applicant and member of local community (Kimmirut), who was satisfied that site had been entirely cleaned and restored.

Date Submitted:

April 7, 2015

Submitted/Prepared by:

Patricia D. Sutherland

Contact Information:

Tel: 613-832-2244

Fax: 613-832-2244

email: psutherl@istar.ca