



WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee		Licensee Representative	
Canada Nunavut Geoscience Office (CNGO)		Dave Mate	
Licence No. / Expiry		Representative's Title	
3BC-HPI1213		P. Geo	
Land / Other Authorizations		Land / Other Authorizations	
N2011N0031		--	
Date of Inspection		Inspector	
17/07/15		Justin HACK	
Activities Inspected			
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other: Culvert	<input checked="" type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage
<input type="checkbox"/> Other: Bridge			

Conditions:		A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected					
Water Use		Condition	Comment	Site Conditions		Condition	Comment	Haz/Mat Management		Condition	Comment
Intake/Screen	NA			Water Management Structures		NA		Storage		NA	
Flow Measure. Device	NA			Culverts / Bridges		NA		Spills		NA	
Source:	NA			Drainage		NA		Spill Plan		NA	
Water Use:	NA			Erosion / Sediment		NA					
Recirculation ( y /n)	NA			Mitigation Measures		NA		Administrative			
				Reclamation Activities		A		Records		NA	
				Materials Storage		NA		Reports		NA	
Waste Disposal				Signage		NA		Plans		A	
Waste Water	NA							Notifications		NA	
Solid Waste	A			Monitoring				Other			
Hazardous Waste	NA			Sample Collection / Analysis		NA					
*The number in the comments field will correspond with specific comments provided below.											
Samples taken by Inspector:				Location(s):							
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No											

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.__)	<input type="checkbox"/> Action Required (s.__)
Pre-inspection			
Nunavut Water Licence #3BC-HPI1213 was issued to CNGO for the use of 50 cubic metres annually of water and the deposit of sewage into a sump. The Report titled, “Summary Report of Land Use Activities for CNGO water licence 3BC-HPI1213 type ‘B’” was submitted on March 14, 2014 and provides a summary of activities conducted and remedial measures taken related to the water licence.			
Observations			
<ul style="list-style-type: none"><li>- An inspection of the site was conducted on July 17, 2015.</li><li>- All sumps were back filled with material and contoured to the original land surface.</li><li>- No other issues related to water use or waste disposal were observed.</li><li>- Reclamation activities were completed as outlined within the report.</li></ul>			
<a href="#">Click here to enter text.</a>			
SECTION 2	<input checked="" type="checkbox"/> Comments (s._2_)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s.__)	<input type="checkbox"/> Action Required (s.__)
No additional clean-up and/or restorative measures are required.			
By way of this report, Aboriginal Affairs and Northern Development Canada hereby notify the Nunavut Water Board a final inspection of water licence 3BC-HPI1213 has been completed.			

Licensee or Representative	Inspector's Name
	Justin Hack
Signature	Signature
Date	Date
	19/10/2015

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

