



WATER USE INSPECTION REPORT

Date: Aug 6, 2011	Licensee Rep. (Name/Title): N/A
Licensee: Eric Tapatai	Licence No.: 3BC-ING0712

The Turravik Outpost Camp is owned by Eric Tapatai. The camp was inactive at the time of the inspection.

WATER SUPPLY

Source(s): Baker Lake	Quantity Permitted: 5 m3/day
Owner:/Operator: Eric Tapatai	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: NA	Storage Structure: NA	Treatment Systems: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

Comments: No one was onsite during the inspection and no water is being used for camp purposes.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): N/A

Natural Water Body:	Continuous Discharge (land or water):	
Seasonal Discharge:	Wetlands Treatment:	Trench:

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: NA
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: Unknown	A&R Plan: Unknown
Discharge: NA	Effluent Discharge Rate: NA	

Comments: The camp was inactive at the time of the inspection.

Solid Waste:

Owner/Operator:

Landfill:	Burn & Landfill: U	Other:
-----------	--------------------	--------

Comments: General waste is stored into several drums around the camp site. Open burning is occurring onsite which is not permitted as per Part D, Item 2 of the water licence.

FUEL STORAGE:

Waste Oil Storage:

Owner/Operator:

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners:	Water within Berms:	Evidence of Leaks:
Drainage Pipes:	Pump Station & Catchments Berm:	
Pipeline Condition:	Condition of Tanks:	

Comments: There are a couple of fuel drums located onsite; the quantity of fuel inside the drums is unknown. Fuel stored onsite should be in secondary containment. Naphtha fuel containers should be back hauled to Baker Lake for proper disposal.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected		Owner /Operator:
		INAC:.None
Signs Posted	SNP: None	Warning:
Records & Reporting: NA		
Geotechnical Inspection: NA		

Non-Compliance of Act or Licence:

- Open burning is not permitted as per Part D, Item 2 of the water licence. All general garbage and hazardous waste must be backhauled for proper disposal.
- A general clean up of the camp should be done and all materials brought back to Baker Lake for disposal.

Ian Rumbolt
Inspector's Name

Sent by E-mail
Inspector's Signature