Field Operations Nunavut Regional Office PO Box 100 Iqaluit, NU X0A 0H0

August 20, 2012

Mr. Max Friesen Department of Anthropology University of Toronto 19 Russel St. Toronto, ON M5S 2S2

RE: NWB Licence No. 3BC-IQA1010

Dear Mr. Friesen,

I recently was present at your site on July 13, 2012. Please find attached the report of my inspection. I found the site to be satisfactory; the garbage nearby clearly pre-exists your licence.

Please feel free to contact me to discuss this if you have any questions.

Thank you,

Eva Paul

Water Resources Officer

Phone: 867-975-4548 Fax: 867-979-6445 Mobile: 867-222-6490

E-mail: Eva.Paul@aandc-aadnc.gc.ca

Andrew Keim, A/Manager, Field Operations, Nunavut Regional Office Cc:

Phyllis Beaulieu, Manager of Licensing, Nunavut Water Board



WATER USE INSPECTION REPORT

Date: July 13 2012	Licensee Rep. (Name/Title): N/A		
Licensee: University of	Toronto	Licence No.:	3BC-IQA1010

WATER SUPPLY

Source(s):	Quantity used: n/a
Owner:/Operator: Max Friesen	

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected **Intake Facilities: NA** Storage Structure: NA **Treatment Systems: Chemical Storage: NA** Flow Meas. Device: **Conveyance Lines: Pumping Stations: NA** Screen: NA NA

Comments: The camp is completely removed.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Outhouse

Natural Water Body: -	Continuous Discharge (land or water): -	
Seasonal Discharge: -	Wetlands Treatment: -	Trench: -

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: A
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: NA	A&R Plan: NA
Discharge: NA	Effluent Discharge Rate: NA	

Comments: No evidence except for the archaeological excavations marks the site.

Solid Waste:

Owner/Operator:

andfill: NA Burn 8	Landfill: NA	Other: Backhaul
--------------------	--------------	-----------------

Comments: Legacy garbage is evident.

FUEL STORAGE:

Waste Oil Storage: None Owner/Operator: Licensee

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: NA	Water within Berms: NA	Evidence of Leaks: NA
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

Comments: No fuel related to this project remains on-site.



Non-Compliance of Act or Licence: None. I recommend this file for closure.

Eva Paul Inspector's Name

Inspector's Signature